

Inspection Photos

Location Name: CAERUS PICEANCE LLC, HYRUP-68S96W/12SWNE

Location ID: 334061

Date: 12/6/2023



Location Entrance – Photo #08023



Wellheads – Photo #08029

Inspection Photos

Location Name: CAERUS PICEANCE LLC, HYRUP-68S96W/12SWNE

Location ID: 334061

Date: 12/6/2023



Separators – Photo #08024



Tank Battery/No Battery Sign – Photo #08025

Inspection Photos

Location Name: CAERUS PICEANCE LLC, HYRUP-68S96W/12SWNE

Location ID: 334061

Date: 12/6/2023



Stored Equipment – Photo #08030



Wildlife Entry Hazard – Photo #08026

Inspection Photos

Location Name: CAERUS PICEANCE LLC, HYRUP-68S96W/12SWNE

Location ID: 334061

Date: 12/6/2023



Lack of Stabilization – Photo #08028



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #08033**