

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/06/2023

Submitted Date:

12/11/2023

Document Number:

708301361

FIELD INSPECTION FORMLoc ID 334061 Inspector Name: Morris, Matthew On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

13 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, CAERUS		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
273852	WELL	SI	09/01/2023	GW	045-10286	HYRUP 12-53	SI
277497	WELL	SI	09/01/2023	GW	045-10706	HYRUP 12-32C	SI
277498	WELL	SI	10/01/2022	GW	045-10705	HYRUP 12-32B	SI
277499	WELL	TA	09/01/2023	GW	045-10704	HYRUP 12-32D	TA

General Comment:**COGCC Inspection Report Summary**

On 12/6/2023 at approximately 12:00, Compliance Inspector Matthew Morris conducted an on-site inspection at CAERUS PICEANCE LLC, HYRUP-68S96W/12SWNE at Location ID #334061 in Garfield County, Colorado.

Normal production operations were observed.

During the inspection, the following compliance issues were observed:

- 1) No battery sign
- 2) Stored equipment near wellheads
- 3) Wildlife entry hazard at PVC piping near tank battery
- 4) Stormwater; refer to Stormwater section

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

LocationOverall Good: ☐**Signs/Marker:**

Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	No battery sign.		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	01/10/2024

Emergency Contact Number:

Comment: 911/(970) 285-2615

Corrective Action:

Date: _____

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	Stored equipment on location near wellheads.		
Corrective Action:	Remove stored equipment to comply with Rule 606.	Date:	12/18/2023
Type	OTHER		
Comment:	Wildlife entry hazard at PVC piping near tank battery.		
Corrective Action:	Install wildlife protective equipment to comply with Rule 608.a.(13).	Date:	12/16/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	

Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 4		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 4		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 273852 Type: WELL API Number: 045-10286 Status: SI Insp. Status: SI**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: _____

Corrective Action: _____ Date: _____

Facility ID: 277497 Type: WELL API Number: 045-10706 Status: SI Insp. Status: SI**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: _____

Corrective Action: _____ Date: _____

Facility ID: 277498 Type: WELL API Number: 045-10705 Status: SI Insp. Status: SI**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: _____

Corrective Action: _____ Date: _____

Facility ID: 277499 Type: WELL API Number: 045-10704 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: _____

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Seeding						
Other	Fail					Insufficient tracking BMPs
		Gravel				
Berms						
Gravel	Fail					Insufficient gravel
Compaction	Fail					Location lacks stabilization
		Compaction				

Comment: [Location surface lacks stabilization with insufficient vehicle tracking BMPs in place to minimize transportation of sediment.](#)

Corrective Action: [Oil and gas operators shall implement and maintain Best Management Practices \(BMPs\) at all oil and gas locations to comply with Rule 1002.](#)

Date: 12/26/2023

Pits: ☒ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	288686	1433580	
	288686	1433580	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708301362	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6352843