

Storm Water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 1-42 (RN1) Pad
Location #: 323989



Location Overview: Location is within Black Bear Habitat area & in close proximity to High Priority/Density/NSO Habitat areas. Location is within Rule 411a Surface Water External Buffer. Location is approximately 480 yards from Beaver Creek.

Section/Township/Range: 1 7S94W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 1-42 (RN1) Pad
Location #: 323989



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 1-42 (RN1) Pad
Location #: 323989



Photo # 9049 Lack of stabilization/compaction/insufficient BMP's



Photo # 9050 Lack of stabilization/compaction/insufficient BMP's

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 1-42 (RN1) Pad
Location #: 323989



Photo # 9051 Lack of stabilization/compaction/insufficient BMP's



Photo # 9052 Lack of stabilization/compaction/insufficient BMP's

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 1-42 (RN1) Pad
Location #: 323989



Photo # 9053 Lack of stabilization/compaction/insufficient BMP's



Photo # 9054 Lack of stabilization/compaction/insufficient BMP's

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 1-42 (RN1) Pad
Location #: 323989



Photo # 9055 Lack of stabilization/compaction/insufficient BMP's



Photo # 9056 Lack of stabilization/compaction/insufficient BMP's

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 1-42 (RN1) Pad
Location #: 323989



Photo # 9057 Lack of stabilization/compaction/insufficient BMP's



Photo # 9058 Lack of stabilization/compaction/insufficient BMP's

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 1-42 (RN1) Pad
Location #: 323989



Photo # 9059 Lack of stabilization/compaction/insufficient BMP's



Photo # 9060 Lack of stabilization/compaction/insufficient BMP's

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 1-42 (RN1) Pad
Location #: 323989



Photo # 9061 Lack of stabilization/compaction/insufficient BMP's



Photo # 9062 Lack of stabilization/compaction/insufficient BMP's

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 1-42 (RN1) Pad
Location #: 323989



Photo # 9063 Lack of stabilization/compaction/insufficient BMP's



Photo #9064 Lack of stabilization/compaction/insufficient BMP's

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 1-42 (RN1) Pad
Location #: 323989



Photo # 9065 Sediment/soils transported into the interim area



Photo #9066 Sediment/soils transported into the interim area