

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403607915

Date Received:

11/28/2023

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10758

Name of Operator: OGRIS OPERATING LLC

Address: PO BOX 53467

City: MIDLAND State: TX Zip: 79710

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

BACA, DAVE

719-859-4066

dbaca@ogrisop.com

WARD, GIENA

719-220-4041

gward@ogrisop.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 695108681

Inspection Date: 09/25/2023

FIR Submit Date: 10/19/2023

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: OGRIS OPERATING LLC

Company Number: 10758

Address: PO BOX 53467

City: MIDLAND State: TX Zip: 79710

### LOCATION - Location ID: 423390

Location Name: APACHE CANYON Number: 20-11 County: LAS ANIMAS

Qtrqtr: NESW Sec: 20 Twp: 34S Range: 67W Meridian: 6

Latitude: 37.067970 Longitude: -104.913739

### FACILITY - API Number: 05-071- -00 Facility ID: 423391

Facility Name: APACHE CANYON Number: 20-11

Qtrqtr: NESW Sec: 20 Twp: 34S Range: 67W Meridian: 6

Latitude: 37.067970 Longitude: -104.913739

### CORRECTIVE ACTIONS:

1 ☒ CA# 185533

Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, remove salt/mineral buildup, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Date: 11/19/2023

Response: CA COMPLETED

Date of Completion: 10/20/2023

Operator Comment: THE WATER LEAK AT THE WELL HEAD WAS STOPPED IMMEDIATELY AND MECHANICAL MAINTENANCE WAS PERFORMED. THE STAINED SOIL WAS REMOVED FROM LOCATION AND FRESH GRAVEL ADDED TO THE WELL PAD. THE SELF INSPECTION PROCESS HAS BEEN REVIEWED.

COGCC Decision: Approved via an AMI

COGCC  
Representative:

2 ☒ CA# 185534

Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals, remove salts/mineral impacted soils, and maintain in good mechanical condition per Rule 608.e.

Date: 11/19/2023

Response: CA COMPLETED

Date of Completion: 11/17/2023

Operator  
Comment: THE MAIN ACCESS ROAD LEADING TO LOCATION HAS BEEN BLADED AND CROWNED TO DIRECT STORMWATER TO THE ROCKED DIVERSION DITCHES. TURN OUTS WERE ALSO ESTABLISHED.

COGCC Decision: Approved via an AMI

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: ALL CORRECTIVE ACTIONS HAVE BEEN COMPLETED, SEE PHOTO LOG FOR DETAILS.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: GIENA ZECHES

Signed: \_\_\_\_\_

Title: ENVIRONMENTAL

Date: 11/28/2023 12:30:14 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403607915	FIR RESOLUTION SUBMITTED
403607921	PHOTO LOG

Total Attach: 2 Files