

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/13/2023

Submitted Date:

12/13/2023

Document Number:

696305499

FIELD INSPECTION FORM

Loc ID 432757	Inspector Name: PETRIE, ERICA	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: 10071 Name of Operator: HIGHPOINT OPERATING CORPORATION Address: 555 17TH ST STE 3700 City: DENVER State: CO Zip: 80202				Findings: 21 Number of Comments 5 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:			
Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
432750	WELL	SI	06/01/2022	OW	123-37263	Pappenheim 6-62-23-0461BH	SI
432751	WELL	PR	01/01/2023	OW	123-37264	Pappenheim 6-62-23-0560BH	PR
432752	WELL	SI	08/01/2023	OW	123-37265	Pappenheim 6-62-23-0659CH	SI
432753	WELL	PR	01/01/2023	OW	123-37266	Pappenheim 6-62-23-0164BH	PR
432755	WELL	PR	11/01/2022	OW	123-37268	Pappenheim 6-62-23-0263BH	PR
432756	WELL	SI	08/01/2023	OW	123-37269	Pappenheim 6-62-23-0362BH	SI
433867	WELL	SI	08/01/2023	OW	123-37826	Pappenheim 6-62-23-0164CDH	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Southeast Crude Oil Tank - Content, Capacity and NFPA Labels; see photos		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	01/15/2024
Type	CONTAINERS		
Comment:	Container at 6-62-23-0164CDH Pumping Unit missing Content Labels; See photos		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	01/15/2024

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Stained Soil at VRU; see photos		
Corrective Action:	For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e."	Date:	12/29/2023
Type	DEBRIS		
Comment:	Tumbleweed Debris build-up at 6-62-23-0164CDH Pumping Unit		
Corrective Action:	Comply with Rule 606	Date:	12/29/2023
Type	UNUSED EQUIPMENT		
Comment:	Unmarked OOSLAT Risers at various Locations on Pad - 2" Risers west of Pumping Unit, 1" Risers at VRU, 2" buired Bull Plugs at Heater Treater. See photos		
Corrective Action:	Complete flowline and crude oil transfer line abandonments to comply with Rule 1105.	Date:	12/18/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

Equipment:				corrective date	
Type: Emission Control Device	# 3				
Comment:					
Corrective Action:					Date:
Type: Bradenhead	# 7				
Comment:	Appear to be plumbed to surface				
Corrective Action:					Date:
Type: Ancillary equipment	# 1				
Comment:	Electrical and Automation Equipment				
Corrective Action:					Date:
Type: Gathering Line	# 2				
Comment:					
Corrective Action:					Date:
Type: Horizontal Heated Separator	# 3				
Comment:					
Corrective Action:					Date:
Type: Vertical Heater Treater	# 1				
Comment:					
Corrective Action:					Date:
Type: VRU	# 1				
Comment:					
Corrective Action:					Date:
Type: Pump Jack	# 7				
Comment:					
Corrective Action:					Date:
Type: Gas Meter Run	# 3				
Comment:					
Corrective Action:					Date:
Type: VRT	# 3				
Comment:					
Corrective Action:					Date:
Type: Bird Protectors	# 15				
Comment:					
Corrective Action:					Date:
Type: Prime Mover	# 7				
Comment:	Electric Motors to run Pumping Units				
Corrective Action:					Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	400 BBLs	STEEL AST		,	

Comment:							
Corrective Action:						Date:	
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity		Permeability (Wall)		Permeability (Base)		Maintenance
Comment:		Shares berm with the Crude Oil Tanks					
Corrective Action:							Date:
Contents	#	Capacity	Type		Tank ID	SE GPS	
PRODUCED WATER	2	400 BBLS	STEEL AST			,	
Comment:							
Corrective Action:							Date:
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity		Permeability (Wall)		Permeability (Base)		Maintenance
Comment:		Shares berm with the Crude Oil Tanks					
Corrective Action:							Date:
Contents	#	Capacity	Type		Tank ID	SE GPS	
CRUDE OIL	8	400 BBLS	HEATED STEEL AST			40.479860,-104.292120	
Comment:							
Corrective Action:							Date:
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity		Permeability (Wall)		Permeability (Base)		Maintenance
Metal	Adequate		Walls Sufficent		Base Sufficient		Adequate
Comment:							
Corrective Action:							Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
Flaring:			
Type	Field Flare		
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 432750 Type: WELL API Number: 123-37263 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

Facility ID: 432751 Type: WELL API Number: 123-37264 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____ Date: _____

Facility ID: 432752 Type: WELL API Number: 123-37265 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

Facility ID: 432753 Type: WELL API Number: 123-37266 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____ Date: _____

Facility ID: 432755 Type: WELL API Number: 123-37268 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____ Date: _____

Facility ID: 432756 Type: WELL API Number: 123-37269 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

Facility ID: 433867 Type: WELL API Number: 123-37826 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Routine Field Inspection. Southeast Crude Oil Tank - Content, Capacity and NFPA Labels. Container at 6-62-23-0164CDH Pumping Unit missing Content Labels. Unmarked OOSLAT Risers at various Locations on Pad - 2" Risers west of Pumping Unit, 1" Risers at VRU, 2" buired Bull Plugs at Heater Treater. Tumbleweed Debris build-up at 6-62-23-0164CDH Pumping Unit. Stained Soil at VRU.	petriee	12/13/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696305500	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6355681