


Inspection Photos
Location Name: State 44-36
Location ID: 306091



Energy & Carbon Management Commission
40.26566, -104.94813, 1494.4m, 203°
12/13/2023 14:36:51

Production facility



Energy & Carbon Management Commission
40.26445, -104.94479, 1489.7m, 353°
12/13/2023 14:39:09

Wellhead

Inspection Photos
Location Name: State 44-36
Location ID: 306091



DCP meter calibration card