

Inspection Photos

Location Name: AMIGO-66N64W/17NWNE

Location ID: 330135



Photo #1

Amigo 17-12 (123-18484) Wellsite

Plugged & Abandoned | PA

Cut / Capped

Flowline is Locked-Out, Tagged-Out | LOTO



Photo #2

Amigo 17-12 Battery site

Inactive | Shut-down

Formerly served:

Amigo 17-12, Gulley 17-15, Uhrich 17-21 ;

Plugged & Abandoned | PA

Equipment Documented; Loc ID: 330135



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: AMIGO-66N64W/17NWNE

Location ID: 330135




Photo #3

Amigo 17-12 Battery site

Inactive | Shut-down

Tank(s): SE corner

Corrective Action: Unnecessary Equipment

All wells have been PA'd; Remove Equipment



Photo #4

Amigo 17-12 Battery site

Inactive | Shut-down

ECD(s), Separator(s)

Corrective Action: Unnecessary Equipment

All wells have been PA'd; Remove Equipment



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: AMIGO-66N64W/17NWNE

Location ID: 330135



Photo #5

Amigo 17-12 Battery site

Inactive | Shut-down

Battery sign

Corrective Action: Unnecessary Equipment

All wells have been PA'd; Remove Equipment



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources