

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/14/2023

Submitted Date:

12/14/2023

Document Number:

696305514

**FIELD INSPECTION FORM**

Loc ID 429977 Inspector Name: PETRIE, ERICA On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 8960  
Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY  
Address: 555 17TH STREET SUITE 3700  
City: DENVER State: CO Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 26 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		Inspections@civiresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
429978	WELL	PR	05/11/2013	OW	123-35985	ANTELOPE F-J-15HNB	PR
438126	WELL	PR	11/01/2014	OW	123-39886	Antelope A-E-15HNB	PR
438127	WELL	PR	06/01/2023	OW	123-39887	Antelope A11-E14-15HNB	PR
438128	WELL	PR	10/27/2014	OW	123-39888	Antelope 11-14-15HNB	PR
438129	WELL	PR	10/26/2014	OW	123-39889	Antelope A11-E14-15HNC	PR
438130	WELL	PR	10/27/2014	OW	123-39890	Antelope A-E-15HNC	PR

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

Type	CONTAINERS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	EAST TANK BATTERY LABELS - #1336 - NFPA and Content. #220404 - Content, Capacity and NFPA. #220403 - NFPA. #220402 - Capacity and Content. #220401 - NFPA. East side of East Tanks - far North Tank - Capacity. Far South Tank - Content, Capacity and NFPA. See photos		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	01/15/2024
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

**Good Housekeeping:**

Type	DEBRIS		
Comment:	Tumbleweed Debris build-up at Maintenance Tank. Lid is open to Atmosphere		
Corrective Action:	Comply Rule 606 Install or repair wildlife protection equipment. Prevent any unauthorized discharge (specify condition if it is E&P waste, improper disposal, trash, etc.) Per Rule 902.b.	Date:	12/29/2023

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Panels		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 14		
Comment:			
Corrective Action:			Date:
Type: VRT	# 2		
Comment:	1 on Eastside and 1 on Westside		
Corrective Action:			Date:
Type: Emission Control Device	# 10		
Comment:	4 on the Eastside and 6 on Westside		
Corrective Action:			Date:
Type: Plunger Lift	# 6		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 6		
Comment:	Appear to be plumbed to surface		
Corrective Action:			Date:
Type: Other	# 1		
Comment:			
Corrective Action:			Date:
Type: Compressor	# 1		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Instrumental Air Unit		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 9		
Comment:	4 on the Eastside and 5 on the Westside		
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	OTHER	BV CONCRETE		,	
Comment:	Maintenance Tank on Southside of Location					
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	60 BBLS	

Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate			
Comment:							
Corrective Action:							Date:
Contents	#	Capacity	Type	Tank ID	SE GPS		
PRODUCED WATER	2	OTHER	BV CONCRETE		,		
Comment:							
Corrective Action:							Date:
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity) 60 BBLs							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Comment: <a href="#">Shares berm with the Crude Oil Tanks</a>							
Corrective Action:							Date:
Contents	#	Capacity	Type	Tank ID	SE GPS		
PRODUCED WATER	2	500 BBLs	STEEL AST		,		
Comment:							
Corrective Action:							Date:
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Comment: <a href="#">Shares berm with the Crude Oil Tanks</a>							
Corrective Action:							Date:
Contents	#	Capacity	Type	Tank ID	SE GPS		
PRODUCED WATER	2	500 BBLs	STEEL AST		,		
Comment:							
Corrective Action:							Date:
<u>Paint</u>							
Condition	Adequate						

Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment: <a href="#">Shares berm with the Eastside Crude Oil Tanks</a>	
Corrective Action:	Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	OTHER	BV CONCRETE		

Comment:	
Corrective Action:	Date:

**Paint**

Condition	Adequate	
-----------	----------	--

Other (Content)	
Other (Capacity) 60 BBLs	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment: <a href="#">Shares berm with the Eastside Crude Oil Tanks</a>	
Corrective Action:	Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	9	500 BBLs	STEEL AST		40.406200,-104.316040

Comment: <a href="#">Westside Tanks</a>	
Corrective Action:	Date:

**Paint**

Condition	Adequate	
-----------	----------	--

Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:	
Corrective Action:	Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	11	500 BBLs	STEEL AST		40.406150,-104.313820

Comment: <a href="#">Eastside Tanks</a>	
Corrective Action:	Date:

<b>Paint</b>				
Condition	Adequate			
Other (Content)				
Other (Capacity)				
Other (Type)				
<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:
<b>Venting:</b>				
Yes/No	NO			
Comment:				
Corrective Action:				Date:
<b>Flaring:</b>				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities									
Facility ID:	429978	Type:	WELL	API Number:	123-35985	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	438126	Type:	WELL	API Number:	123-39886	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	438127	Type:	WELL	API Number:	123-39887	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	438128	Type:	WELL	API Number:	123-39888	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	438129	Type:	WELL	API Number:	123-39889	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	438130	Type:	WELL	API Number:	123-39890	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<a href="#">Routine Field Inspection. East Tank Battery - Tank Labels</a>	petrie	12/14/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696305515	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6357102">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6357102</a>