

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL GARDNER (PK-21) Pad

Location ID: 334769



Photo # 9743 From entrance to location



Photo # 9744 From entrance to location

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL GARDNER (PK-21) Pad

Location ID: 334769




Photo # 9745 Location



Photo # 9746 Location



Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL GARDNER (PK-21) Pad

Location ID: 334769



Photo # 9747 Location



Photo # 9748 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL GARDNER (PK-21) Pad

Location ID: 334769



Photo # 9749 Location



Photo # 9750 Barbed wire fence needs maintenance/wildlife hazard

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL GARDNER (PK-21) Pad

Location ID: 334769



Photo # 9751 Barbed wire fence needs maintenance/wildlife hazard



Photo # 9752 Barbed wire fence needs maintenance/wildlife hazard

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL GARDNER (PK-21) Pad

Location ID: 334769



Photo # 9753 Rupture disc vent line lacks cap



Photo # 9754 Rupture disc vent line lacks cap

