

Inspection Photos

Location Name: CAERUS PICEANCE LLC SAVAGE RE1 Pad

Location #: 334639



Photo # 9179 From entrance to location



Photo # 9180 Location



Inspection Photos

Location Name: CAERUS PICEANCE LLC SAVAGE RE1 Pad

Location #: 334639



Photo # 9181 Location



Photo # 9182 Location



Inspection Photos
Location Name: CAERUS PICEANCE LLC SAVAGE RE1 Pad
Location #: 334639



Photo # 9183 Location



Photo # 9184 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC SAVAGE RE1 Pad

Location #: 334639

Dec 11, 2023 at 11:04:41 AM



Photo # 9185 Location

Dec 11, 2023 at 11:05:09 AM



Photo # 9186 Location



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: CAERUS PICEANCE LLC SAVAGE RE1 Pad

Location #: 334639



Photo # 9187 Location



Photo # 9188 Location



Inspection Photos

Location Name: CAERUS PICEANCE LLC SAVAGE RE1 Pad

Location #: 334639



Photo # 9189 PRV vent lines lack caps



Photo # 9190 PRV vent line lacks cap

Inspection Photos

Location Name: CAERUS PICEANCE LLC SAVAGE RE1 Pad

Location #: 334639



Photo # 9191 PRV vent line lacks cap



Photo # 9192 PRV vent line lacks cap

