

**Storm Water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC SAVAGE RE1 Pad**  
**Location #: 334639**



**Location Overview: Location is within High  
Priority/Density/Black Bear Habitat areas. Location is in close  
proximity to Rule 411a Surface Water External Buffer  
Section/Township/Range: 1 7S94W**

**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC SAVAGE RE1 Pad**  
**Location #: 334639**



**North West corner of location.**



**North East corner of location.**



**South West corner of location.**



**South East corner of location.**

**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC SAVAGE RE1 Pad**  
**Location #: 334639**



**Photo # 9193 Lack of stabilization/compaction/insufficient BMP's**

**Photo # 9194 Lack of stabilization/compaction/insufficient BMP's**

**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC SAVAGE RE1 Pad**  
**Location #: 334639**



**Photo # 9195 Lack of stabilization/compaction/insufficient BMP's**

**Photo # 9196 Lack of stabilization/compaction/insufficient BMP's**

**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC SAVAGE RE1 Pad**  
**Location #: 334639**



**Photo # 9197 Lack of stabilization/compaction/insufficient BMP's**

**Photo # 9198 Lack of stabilization/compaction/insufficient BMP's**

**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC SAVAGE RE1 Pad**  
**Location #: 334639**



**Photo # 9199 Lack of stabilization/compaction/insufficient BMP's**



**Photo # 9200 Lack of stabilization/compaction/insufficient BMP's**

**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC SAVAGE RE1 Pad**  
**Location #: 334639**



**Photo # 9201 Lack of stabilization/compaction/insufficient BMP's**

**Photo # 9202 Lack of stabilization/compaction/insufficient BMP's**