

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/12/2023

Submitted Date:

12/15/2023

Document Number:

708902532**FIELD INSPECTION FORM**Loc ID 334780 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: 1058 COUNTY ROAD 215City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
456921	Domestic Tap	AC	08/28/2018		-	Domestic Tap 33NESW	AC

**General Comment:****CECMC Inspection Report Summary**

On 12/12/2023 at approximately 10:39 hours, I, Compliance Specialist, Wayne Smelser  
Conducted a domestic tap inspection at TEP ROCKY MOUNTAIN LLC Domestic Tap 33NESW  
Location # 334780 in Garfield County Colorado.  
While there, I observed the domestic tap is derived from TEP sales line.

This is a summary of inspection report

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective ActionL		Date:	

Overall Good: ☐

Emergency Contact Number:	
Comment:	<input type="text"/>
Corrective Action:	<input type="text"/> Date: _____

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Other	# 1		
Comment:	Domestic tap		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	456921	Type:	Domestic Tap	API Number:	-	Status:	AC	Insp. Status:	AC
Producing Well									
Comment:	While there, I observed the domestic tap is derived from TEP sales line. The line ties into a fluid knock out, following the knock out there's a little joe regulator. All fittings appear to be adequate.								
	No PRV or odorizer observed								
Corrective Action:								Date:	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Domestic tap inspection only](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<a href="#">Domestic tap inspection only</a>	smelserw	12/15/2023

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708902533	Inspection 708902532 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6358471">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6358471</a>