

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, S.PARACHUTE TBI-67S96W/36NESE

Location ID: 334080

Date: 12/12/2023



Location Entrance – Photo #08141



Wellheads/Gas Lifts – Photo #08142

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, S.PARACHUTE TBI-67S96W/36NESE

Location ID: 334080

Date: 12/12/2023



Separators – Photo #08149



Tank Battery – Photo #08144

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, S.PARACHUTE TBI-67S96W/36NESE

Location ID: 334080

Date: 12/12/2023



Stored Equipment/Supplies – Photo #08145



Leaking Load Line Connection – Photo #08146

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, S.PARACHUTE TBI-67S96W/36NESE

Location ID: 334080

Date: 12/12/2023



Leaking and Uncapped Load Line – Photo #08147



Lack of Stabilization – Photo #08143

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, S.PARACHUTE TBI-67S96W/36NESE

Location ID: 334080

Date: 12/12/2023



**Lack of Stabilization – Photo #08148**



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit  
– Photo #08154**