

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

403627644

Date Received:

12/18/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

8 of 8 CAs from the FIR responded to on this Form

8 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10797

Name of Operator: DESERT EAGLE OPERATING LLC

Address: 17101 PRESTON RD SUITE 105

City: DALLAS State: TX Zip: 75248

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Costa, Ryan</u>		<u>ryan.costa@state.co.us</u>
<u>Butler, Brad</u>	<u>972-345-9195</u>	<u>butleroil@yahoo.com</u>
<u>Bulf, Cathy</u>		<u>cathybulf@gmail.com</u>
<u>Sanchez, Chris</u>		<u>chris.sanchez@state.co.us</u>
<u>Beardslee, Tom</u>		<u>tom.beardslee@state.co.us</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 713600421

Inspection Date: 11/21/2023

FIR Submit Date: 11/28/2023

FIR Status: _____

Inspected Operator Information:

Company Name: DESERT EAGLE OPERATING LLC

Company Number: 10797

Address: 17101 PRESTON RD SUITE 105

City: DALLAS State: TX Zip: 75248

LOCATION - Location ID: 484358

Location Name: Red Rocks Number: 1-16 County: LAS ANIMAS

Qtrqtr: NENE Sec: 1 Twp: 30S Range: 55W Meridian: 6

Latitude: 37.464488 Longitude: -103.518825

FACILITY - API Number: 05-071-

-00

Facility ID: 484677

Facility Name: Red Rocks Number: 1-16

Qtrqtr: NENE Sec: 1 Twp: 30S Range: 55W Meridian: 6

Latitude: 37.464488 Longitude: -103.518825

CORRECTIVE ACTIONS:

1 CA# 188519

Corrective Action: Comply with Rule 201.a. for safety.

Date: 11/21/2023

Response: CA COMPLETED

Date of Completion: 12/01/2023

Operator Comment: In compliance with Rule 201.a., a visible barrier fence was installed prior to backfilling the trench.

COGCC Decision: _____

COGCC Representative: _____

2 CA# 188520

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C
Comply with 1002.e. surface disturbance minimization.

Date: 11/21/2023

Response: CA COMPLETED

Date of Completion: 12/07/2023

Operator Comment: Soils along the recently graded road was stabilized to prevent erosion in compliance with Rule 1002.f.(2)C. The road will be maintained to maintained and stabilized to prevent vehicle rutting and erosion

COGCC Decision: _____

COGCC Representative: _____

3 CA# 188521

Corrective Action: Install sign to comply with Rule 605.d.

Date: 11/21/2023

Response: CA COMPLETED

Date of Completion: 12/01/2023

Operator Comment: Sig was installed at the wellhead to comply with Rul 605.d.

COGCC Decision: _____

COGCC Representative: _____

4 CA# 188522

Corrective Action: Comply with Rule 606.

Date: 11/21/2023

Response: CA COMPLETED

Date of Completion: 12/08/2023

Operator Comment: In compliance with Rule 606, tree debris along the flowline and at the location were removed.

COGCC Decision: _____

COGCC Representative: _____

5 CA# 188523

Corrective Action: Comply with 1002.b. rules for soil removal and segregation.
Comply with 1002.c. rules for protection of soils.

Date: 11/21/2023

Response: CA COMPLETED

Date of Completion: 12/06/2023

Operator Comment: The flowline trench was filled with soil removed from the trench, lastly with topsoil. The operator has reviewed with field personnel Rule 1002.b., for soil removal and segregation to assure compliance for all operations that require soil segregation. Rock was removed from the location. Drill cuttings were removed from the lined and berm drill cuttings area and disposed of in compliance with Rule 905.b.(1) and (3), Rule 905.g.(1).c, and Rule 905.e.(1)a.

COGCC Decision: _____

COGCC
Representative:

6 CA# 188524

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)

Date: 11/21/2023

Response: CA COMPLETED

Date of Completion: 12/12/2023

Operator
Comment:

Rule 1002.f.(2), loose disturbed soils along the flowline disturbance were stabilized to minimize erosion.

COGCC Decision: _____

COGCC
Representative:

7 CA# 188525

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)

Date: 11/21/2023

Response: CA COMPLETED

Date of Completion: 12/06/2023

Operator
Comment:

Per Rule 1002.f.9(2), BMP repairs have been made to the displaced and damaged wattles. Wattles buried in drill cuttings were disposed of in compliance with Rule 905.

COGCC Decision: _____

COGCC
Representative:

8 CA# 188526

Corrective Action: Comply with Rule 905. for Management of E&P Waste. Clean up and contain.

Date: 11/21/2023

Response: CA COMPLETED

Date of Completion: 12/06/2023

Operator
Comment:

To expedite the management of the drill cuttings and prevent any further releases, in compliance with Rule 905.b.(1) and (3), Rule 905.g.(1).c., and Rule 905.e.(1) a., the drill cuttings have been managed as Oily Waste and have been removed from the location and disposed at an approved waste facility.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: The recently graded access road was stabilized to prevent erosion - attachment Access Road Stabilization.pdf The sign was installed properly at the wellhead - attachment RR 1-16 Wellhead Photo.pdf The open trench was first provided a barrier safety fence and then backfilled shortly thereafter - attachment RR 1-16 Wellhead - Trench Area.pdf The tree debris along the flowline and at the location was removed - attachment Red Rocks 1-16 Location Clean Up.pdf Rocks were removed from the location, the trench was backfilled with soils removed from the trench, and topsoil was segregated to the extent possible and placed on top. The location was ripped and seeded. Wattles were placed in their original position and repaired/replaced where needed; wattles in the drill cuttings pile were removed - attachment RR 1-16 Erosion BMP Corrected - Wattles.pdf. The high winds at the location appeared to cause drill cuttings that were stored on a lined and bermed area to drift across the site. To expedite the management of the drill cuttings and prevent any further releases, in compliance with Rule 905.b.(1) and (3), Rule 905.g.(1).c., and Rule 905.e.(1) a., the drill cuttings have been managed as Oily Waste and have been removed from the location and disposed at an approved waste facility - attachment RR 1-16 Manifesto and Land Fill Receipt.pdf

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name:

Signed:

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403628240	RR 1-16 Flowline BMP Erosion Control Photo
403628243	RR 1-16 Location BMP Erosion Control - Wattle Repair
403628244	RR 1-16 Debris Removal Lease and Flowline Photo
403628247	RR 1-16 Debris Removed
403628260	RR 1-16 Sign
403628262	RR 1-16 Flow Line BMP
403628269	RR 1-16 Open Excavation Remediated
403628275	Access Road Stabilization
403628287	Drill Cuttings Manifesto and Disposal Receipts

Total Attach: 9 Files