

# Inspection Photos

API: 011-06032

Operator: STRACHAN EXPLORATION INC

Inspection Date: 12/15/2023

County: Bent



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing west toward the location. There are tall undesirable weeds at the location that need to be controlled and removed.





## Inspection Photos



**Photo 2.** Facing west toward the location. There are tall undesirable weeds at the location that need to be controlled and removed.





## Inspection Photos



**Photo 3.** There are plastic drums with no labeling and one appears to be empty and not in use.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

## Inspection Photos



**Photo 4.** There is no secondary containment of the elevated metal container.





## Inspection Photos



**Photo 5.** Facing toward the tank battery. There is insufficient secondary containment to contain a spill. The sign at the tank does not reflect the current Operator sand is faded



## Inspection Photos



**Photo 6.** Facing northwest at the location. The weeds around the location need to be controlled.





## Inspection Photos




**Photo 7.** There is a dripping leak at the separator and stained soils.





## Inspection Photos



**Photo 8.** Facing toward the well. There is an uncapped pipe riser shown at red arrow.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API: 011-06032 | Date: 12/15/2023