

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/18/2023

Submitted Date:

12/18/2023

Document Number:

696305536

FIELD INSPECTION FORM

Loc ID: 413458 Inspector Name: PETRIE, ERICA On-Site Inspection: 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 8960
Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY
Address: 555 17TH STREET SUITE 3700
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 8 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		Inspections@civiresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
412528	WELL	TA	06/02/2021	GW	123-30512	ANTELOPE 14-19	TA

General Comment:

[Follow-Up Inspection to 696305116 dated 07.17.2023](#)

Location

Overall Good:

Signs/Marker:

Type	CONTAINERS		
Comment:	Chemical Container at Gas Lift Injection Meter House missing Label; see photos		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	01/19/2024
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	<input type="text"/>
Corrective Action:	<input type="text"/>		

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unmarked OOSLAT Risers at 14-19 Wellhead; see photos		
Corrective Action:	Complete flowline and crude oil transfer line abandonments to comply with Rule 1105.	Date:	01/02/2024

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Panels		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 412528 Type: WELL API Number: 123-30512 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: TA - Since 06.02.2021. MIT - 03.25.2021
Form 6A - 403213997 with a Plug Due Date of 12.31.2029

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
Routine Field Follow-Up Inspection. Tumbleweeds have been removed and Riser on Eastside of Location has been tagged. New Corrective Actions: Unmarked OOSLAT Risers at 14-19 Wellhead. Chemical Container at Gas Lift Injection Meter House is missing Labels.	petrie	12/18/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696305537	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6360814