

Location

Overall Good:

Signs/Marker:			
Type	OTHER		
Comment:	Location entrance is adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type			
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 240774 Type: WELL API Number: 123-08562 Status: SI Insp. Status: SI

Cement

Cement Contractor

Contractor Name: Axis Energy

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): 3,102' to 2,794'

Cement Volume (sx): 105

Good Return During Job: YES

Cement Type: G

Comment: Brigade Rig 5 RU over well with Axis Energy Services RU to Pump a Stub Plug from 3,102 ft. to 2,794 ft. (Casing cut at 3,000 ft.) with 105 sxs of 15.8 lbs Type G cement with good returns to the tanks.

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: 12/07/2023

Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 44

Fluid Type: WATER AND GAS

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On Tuesday 12-19-2023 at approximately 1420 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: Form 42 MIRU Doc # 403616987 & Form 42 PA Doc # 403616986 Operator: Civitas/Crestone Peak Resources Location name: Location ID #318173 Well Name: McCoy 1 API # 05-123-08652 County: Weld Weather: Clear, partly cloudy. Location: Dry. While there, I observed a wellsite, with active WO/PA operations at the time of the inspection. During this inspection, I observed no compliance issues: See attached photos. I spoke with Eduardo Chavez Civitas WS Supervisor about current operations (Pumping the Stub plug). No follow up site inspection is needed to ensure that the addressed Compliance issues comply with ECMC rules</p>	revasr	12/19/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702402646	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6362599