

# Final Reclamation and Stormwater Inspection

Date: 12/6/23

Operator: Noble Energy Inc. - 100322

Location ID: 330481

Inspection Document #: 713900157

Weld County, CO

Logan Hansen  
Reclamation Specialist, ECMC



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Western 13-35  
Location ID: 330481



Colorado Energy & Carbon Management  
Commission  
Weld County  
+40.3561, -104.8695  
263° W  
12/6/23, 2:05 PM



Colorado Energy & Carbon Management  
Commission  
Weld County  
+40.3552, -104.8694  
173° S  
12/6/23, 2:13 PM

**Photo 1.** The photo was taken at the location entrance facing West. The photo illustrates the operator signage.

**Photo 2.** The photo was taken at the well entrance facing South. The photo illustrates the access road is dominated by kochia and russian thistle and has not been re-contoured or graded.

Inspection Photos  
Location Name: Western 13-35  
Location ID: 330481



**Photo 3.** The photo was taken along the access road facing South. The photo illustrates pervasive erosion that ran along the majority of the access road.

**Photo 4.** The photo was taken along the access road facing Northwest. The photo illustrates large rill erosion building to gully erosion in the following photos.

Inspection Photos  
Location Name: Western 13-35  
Location ID: 330481



Colorado Energy & Carbon Management  
Commission  
Weld County  
+40.3537, -104.8689  
27° NE  
12/6/23, 2:17 PM



Colorado Energy & Carbon Management  
Commission  
Weld County  
+40.3538, -104.8688  
235° SW  
12/6/23, 2:18 PM

**Photo 5.** The photo was taken along the access road facing Northeast. The photo illustrates a large gully erosional feature that has blown out the road and run into the drainage below.

**Photo 6.** The photo was taken below the access road facing Southwest. The photo illustrates the bottom side of the road blow out described in photo 5.

Inspection Photos  
Location Name: Western 13-35  
Location ID: 330481



**Photo 7.** The photo was taken at the well location facing Southeast. The photo illustrates the pad is still apparent as well as there being erosion and undesirable vegetation throughout. Reclamation has not been started on the location or access road.

**Photo 8.** The photo was taken at the well location facing North. The photo illustrates another erosional feature on the South end of the still existing pad.

Inspection Photos  
Location Name: Western 13-35  
Location ID: 330481



Colorado Energy & Carbon Management  
Commission  
Weld County  
+40.3544, -104.8691  
57° NE  
12/6/23, 2:41 PM



Colorado Energy & Carbon Management  
Commission  
Weld County  
+40.3556, -104.8680  
176° S  
12/6/23, 3:25 PM

**Photo 9.** The reference photo was taken near the well location facing Northeast.

**Photo 10.** The photo was taken at the tank battery location facing South. The photo illustrates proper fencing as well as a gravel berm surrounding the location.

Inspection Photos  
Location Name: Western 13-35  
Location ID: 330481



**Photo 11.** The photo was taken at the tank battery location facing North. Refer to the comment for photo 10.

**Photo 12.** The photo was taken at the tank battery location facing East. The photo illustrates erosion occurring under the concrete pad of some oil and gas equipment.