

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/14/2023

Submitted Date:

12/14/2023

Document Number:

696305510

FIELD INSPECTION FORMLoc ID 466172 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

15 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
466171	WELL	PR	08/04/2021	OW	123-50287	STATE ANTELOPE Y44-E14-13HNB	PR
466173	WELL	PR	07/12/2021	OW	123-50288	STATE ANTELOPE V-B-13HNB	PR
466174	WELL	PR	07/12/2021	OW	123-50289	STATE ANTELOPE V41-B11-13HNC	PR
466175	WELL	PR	07/12/2021	OW	123-50290	STATE ANTELOPE 42-12-13HNC	PR
466176	WELL	PR	08/04/2021	OW	123-50291	STATE ANTELOPE Y-E-13HNC	PR
466177	WELL	PR	07/12/2021	OW	123-50292	STATE ANTELOPE X44-D14-13HNC	PR
466178	WELL	PR	07/12/2021	OW	123-50293	STATE ANTELOPE W42-C12-13HNB	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	CONTAINERS		
Comment:	Container at Gas Lift Injection Meter Houses is missing Label; see photos		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	01/15/2024
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Panels		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 7		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 15		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Line Heater		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 7		

Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 7		
Comment:	Appear to be plumbed to surface		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLs	STEEL AST		40.400750,-104.262950	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No			
Comment:			
Corrective Action:	Date:		

Flaring:

Type			
Comment:			
Corrective Action:	Date:		

Inspected Facilities									
Facility ID:	466171	Type:	WELL	API Number:	123-50287	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	466173	Type:	WELL	API Number:	123-50288	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	466174	Type:	WELL	API Number:	123-50289	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	466175	Type:	WELL	API Number:	123-50290	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	466176	Type:	WELL	API Number:	123-50291	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	466177	Type:	WELL	API Number:	123-50292	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	466178	Type:	WELL	API Number:	123-50293	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
COGCC Comments									
Comment						User	Date		
Routine Field Inspection. Chemical Container at Gas Lift Injection Meters is missing Labels					petrie	12/14/2023			

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403625743	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6357125
696305511	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6357100