

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/05/2023

Submitted Date:

12/14/2023

Document Number:

707602182**FIELD INSPECTION FORM**

Loc ID 330135	Inspector Name: Evins, Bret	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 16 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
------------------	--------------------------------	---	-------------------	--

Operator Information:
 OGCC Operator Number: 100322
 Name of Operator: NOBLE ENERGY INC
 Address: 2001 16TH STREET SUITE 900
 City: DENVER State: CO Zip: 80202

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:			
Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
250681	WELL	TA	02/01/2022	GW	123-18484	AMIGO 17-12	PA

General Comment: This is a WELL / BATTERY inspection. Well(s): 1: Plugged & Abandoned PA. Battery: Inactive Shut-down. Centralized Battery formerly served 3 Location IDs (330135, 302597, 331973). (Well(s): 3: Plugged & Abandoned PA). Reference: A.) Field Inspection Report doc. #707602182 and/or Location ID #330135 for PA Well(s), Battery / Facility, Equipment info. B.) Field Inspection Report doc. #707602184 and/or Location ID #302597 for PA Well(s) info. C.) Field Inspection Report doc. #707602186 and/or Location ID #331973 for PA Well(s) info.

Location				
Lease Road:				
Type	Access			
comment:	Adequate			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	TANK LABELS/PLACARDS			
Comment:				
Corrective Action:				Date:
Type	BATTERY			
Comment:	OOSLAT / LOTO All Inactive Battery Equipment.			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Good Housekeeping:				
Type	UNUSED EQUIPMENT			
Comment:	Unnecessary equipment at Inactive Battery site. ALL wells formerly serving Inactive Battery site have been PA'd. Unnecessary equipment includes: ALL Produced Oil & H2O tank(s), vault(s), Separator(s), ECD(s), Gas meter run(s), riser(s), etc. Refer to Rule 606 for guidance.			
Corrective Action:	*Remove unnecessary equipment from Inactive Battery site. Comply with Rule 606. Corrective Action date: 05/15/2024. (153 days). See photo(s) #3, 4, 5. *Please attach photo(s) to FIRR to verify Corrective Action(s) have been resolved.			Date: 05/15/2024
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:	Iron panel.			
Corrective Action:				Date:
Type	SEPARATOR			

Comment: Surrounded by earth berms.			
Corrective Action:		Date:	
Equipment:			corrective date
Type: Plunger Lift	# 0		
Comment: Well Plugged & Abandoned PA. Equipment removed.			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment: Gas Sales: Calibration card(s) indicates calibration > 1 year. Last calibration: 05/28/2021. Inactive, NO production.			
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment: 1: Crude storage vapor line combustor(s). Controls crude oil tank(s) vapors. Pilots: OFF Shut-down. 1: Separator vapor line combustor(s). Controls separator(s) vapors. Pilots: OFF Shut-down.			
Corrective Action:		Date:	
Type: Other	# 1		
Comment: OOSLAT / LOTO Flowline valve at PA wellsite.			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment: Battery site: 2: ECD scrubber(s).			
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	<100 BBLS	CONCRETE SUMP/VAULT		,
Comment:					
Corrective Action:		Date:			

Paint

Condition	
Other (Content)	
Other (Capacity)	60 Bbls.
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:		Berms shared w/ crude oil tank(s), produced H2O vault(s).						
Corrective Action:							Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS			
CRUDE OIL	2	300 BBLs	STEEL AST		40.492396,-104.572063			
Comment:		Equalizer line(s) connect crude oil tank(s).						
Corrective Action:							Date:	
Paint								
Condition	Adequate							
Other (Content)								
Other (Capacity)								
Other (Type)								
Berms								
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance				
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate				
Comment:		Berms shared w/ crude oil tank(s), produced H2O vault(s).						
Corrective Action:							Date:	
Venting:								
Yes/No	NO							
Comment:								
Corrective Action:						Date:		
Flaring:								
Type								
Comment:								
Corrective Action:						Date:		

Inspected Facilities									
Facility ID:	250681	Type:	WELL	API Number:	123-18484	Status:	TA	Insp. Status:	PA

--

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>CECMC Inspection Report Summary:</p> <p>On TUE 12/05/2023 at approximately 14:42 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: NOBLE ENERGY INC Location Name: AMIGO-66N64W/17NWNE Location ID: 330135 Well Name(s): Amigo 17-12. API: 123-18484. Location County: Weld County, Colorado Weather: Mostly Sunny, damp from prior storm.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Battery: Inactive Shut-down.</p> <p>Centralized Battery formerly served 3 Location IDs (330135, 302597, 331973). (Well(s): 3: Plugged & Abandoned PA).</p> <p>Reference: A.) Field Inspection Report doc. #707602182 and/or Location ID #330135 for PA Well(s), Battery / Facility, Equipment info. B.) Field Inspection Report doc. #707602184 and/or Location ID #302597 for PA Well(s) info. C.) Field Inspection Report doc. #707602186 and/or Location ID #331973 for PA Well(s) info.</p> <p>WELL STATUS COMMENT: Plugged & Abandoned PA. Form 6-SRA NOT filed, pending. Plugging, cut/cap date: 11/30/2023. Plugged & Abandoned PA well GPS coordinates: 40.492015 / -104.572405</p> <p>During this inspection the following possible compliance issue(s) were observed: 1.) Unnecessary equipment at Inactive Battery site. ALL wells formerly serving Inactive Battery site have been PA'd. Unnecessary equipment includes: ALL Produced Oil & H2O tank(s), vault(s), Separator(s), ECD(s), Gas meter run(s), riser(s), etc. Refer to Rule 606 for guidance. *Remove unnecessary equipment from Inactive Battery site. Comply with Rule 606. Corrective Action date: 05/15/2024. (153 days). See photo(s) #3, 4, 5.</p> <p>*Please attach photo(s) to FIRR to verify Corrective Action(s) have been resolved.</p> <p>*A follow up on this site inspection will be conducted to ensure that compliance issues have been corrected to comply with CECMC rules.</p> <p>This is a summary of the inspection report.</p>	evinsb	12/14/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403625784	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6357182
707602183	Site photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6357108