

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/11/2023

Submitted Date:

12/14/2023

Document Number:

708902518

FIELD INSPECTION FORM

Loc ID 334638	Inspector Name: Smelser, Wayne	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 20 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: 10456 Name of Operator: CAERUS PICEANCE LLC Address: 1001 17TH STREET #1600 City: DENVER State: CO Zip: 80202				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:			
Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	
Toews, Wesley		wtoews@blm.gov	

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211441	WELL	SI	07/01/2023	GW	045-07201	SAVAGE 1-32	SI
271832	WELL	PR	01/12/2005	GW	045-09966	SAVAGE FEDERAL 1-15A (RK1)	PR

General Comment:

CECMC Inspection Report Summary
 On 12/11/2023 at approximately 10:37 hours, I, Compliance Specialist, Wayne Smelser
 Conducted a follow up inspection at CAERUS PICEANCE LLC SAVAGE RK1 Pad.
 Location # 334638 in Garfield County Colorado.
 Please refer to inspection 708901917 conducted on 10/09/2023, previous corrective actions have been completed.
 Location is within Black Bear Habitat area & in close proximity to High Priority/Density/NSO Habitat areas.
 Location is within Rule 411a Surface Water Intermediate Buffer.
 Location is approximately 379 yards from Beaver Creek.
 While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Stormwater - Lack of stabilization/compaction/insufficient BMP's on location & lease road with a CA date of 12/29/2023

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.
 This is a summary of inspection report.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-2615

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	Summit Midstream - pipe rail fence		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Barbed wire		
Corrective Action:		Date:	

Equipment:

Type: Other	# 1		corrective date
Comment:	Telemetry		

Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:	Pressure transducers located on all bradenhead. All bradenhead valves are accessible.		
Corrective Action:		Date:	
Type: Plunger Lift	# 2		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
METHANOL	1	1000 GAL	STEEL AST		,	
Comment:	Centralized containment					
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent		
Comment:	Snow in containment			
Corrective Action:			Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	300 BBLS	STEEL AST		,	
Comment:	Centralized containment					
Corrective Action:			Date:			

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent			
Comment: Snow in containment					
Corrective Action:				Date:	

Venting:					
Yes/No	NO				
Comment:					
Corrective Action:			Date:		

Flaring:					
Type					
Comment:					
Corrective Action:			Date:		

--	--	--	--	--	--

Inspected Facilities									
Facility ID:	211441	Type:	WELL	API Number:	045-07201	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder:									
Comment: Shut In									
Last produced June 2023									
Corrective Action:									
Date:									
Facility ID:	271832	Type:	WELL	API Number:	045-09966	Status:	PR	Insp. Status:	PR
Producing Well									
Comment: Producing, well on plunger lift									
Corrective Action:									
Date:									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						Sparse
		Compaction	Fail			Lack of stabilization/compaction/insufficient BMPs
Compaction	Fail					Lack of stabilization/compaction/insufficient BMPs
		Culverts				
		Gravel				Sparse in sections
		Ditches				

Comment: 1. Lack of stabilization/compaction/insufficient BMP's on location

2. Lack of stabilization/compaction/insufficient BMP's on lease road near entrance to location

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved.

Date: 12/29/2023

Pits: ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Please refer to Stormwater for observed compliance issues.	smelserw	12/14/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
403625969	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6357498
708902519	Inspection 708902518 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6357496
708902520	Inspection 708902518 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6357497