

# Work Completion Report

Contractor: Peerless

## JOB DETAILS

Job Name	Month/Season	Completed By	Completion Date
WALTERS 1-8HZ		Armando Munoz	12/19/2023

Work Summary	Reclamation Type	Land Use
Repaired erosion formed throughout the slopes of the facility and associated access road.	Stormwater	Active Pad

One-Call Number	Red Zone Rep	Red Zone Date

## WORK TASK

Task Name	Priority	COGCC Compliance	Task Location and Notes/Instructions
Stormwater Repairs	High	No	Location(s): Walters_4N67W21P Notes: Repair erosion formed throughout slopes of facility and associated access road. Blade and/or skid needed. NO DIGGING.

## COMPLETION DETAILS

Total Area Affected: **1.85 acres**  
 Seed Mix: **None used**  
 Crop Type: **Corn**  
 Soil Type: **Clay Loam**  
 Stabilization Date: **12/19/2023**  
 Seeding Date:  
 Mulch: **None**  
 Straw Bales: **NA**  
 Soil Amendment Type: **None**  
 Soil Amendment Rate: **NA**  
 Imported Top Soil: **NA**  
 Top Soil Source: **NA**  
 General Notes:

LOCATION INFO

---

Location(s) – Name: Walters\_4N67W21P

COGCC ID: **448255**

Well APIs at Location: **12343820 12343821 12343822 12343823 12343824 12343825 12343826 12343827**

Land Rep:

Land Owner: **Ron Walter**

Rec Contractor PO(s): **Peerless: 4501724434**

Vendor PO(s):

Billing Notes: **DJ-L0979**

Legal Address: **(WELD) SESW 21 4N67W**

Topsoil Source:

Variance Notes:

Private Utility Notes:

Wildlife Restrictions:

General Notes:

COGCC Doc #'s:

Initial Reclaim Complete Date:

Maint. Reclaim Complete Date:

PHOTOS

Photo Name: Site Map

Description:

Photo Name: Site Reference

Description:



Photo Name: Pre-Completion

Description:



Photo Name: Post-Completion

Description:



Photo Name: Walter's  
Description:



Photo Name: Walter 2

Description:



Photo Name: Walter's 3

Description:



Photo Name: Walter 5

Description:

