

**Antler Energy LLC
Amoco Federal 21-1
Loc ID: 312970**



Entrance sign when replaced will require additional information.



Entrance to location

**Antler Energy LLC
Amoco Federal 21-1
Loc ID: 312970**



Exhaust staining



Debris from previous inspection

**Antler Energy LLC
Amoco Federal 21-1
Loc ID: 312970**



Wellhead sign missing required information



Debris still on location

**Antler Energy LLC
Amoco Federal 21-1
Loc ID: 312970**



Unit still leaking oil on equipment and into soil



Pit not in use. No pit ID.

**Antler Energy LLC
Amoco Federal 21-1
Loc ID: 312970**



Debris and unused equipment still on location



Open end tank valve still lacking plug

**Antler Energy LLC
Amoco Federal 21-1
Loc ID: 312970**



Open end tank valve still lacking plug



Unresolved wildlife mitigation

**Antler Energy LLC
Amoco Federal 21-1
Loc ID: 312970**



Unresolved wildlife mitigation



Staining not cleaned up

**Antler Energy LLC
Amoco Federal 21-1
Loc ID: 312970**



Sign at tank battery still unresolved

No tank labels installed.