

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403633935

Date Received:
12/21/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10690
Name of Operator: IMPETRO RESOURCES LLC

Address: 558 CASTLE PINES PKWY UNIT B-4

City: CASTLE PINES State: CO Zip: 80108

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Pesicka, Conor</u>		<u>conor.pesicka@state.co.us</u>
<u>Burn, Diana</u>		<u>diana.burn@state.co.us</u>
<u>MacLaren, Joe</u>		<u>joe.maclaren@state.co.us</u>
<u>Bongers, Brent</u>	<u>(361) 935-5633</u>	<u>bbongers@impetroresources.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 688307134

Inspection Date: 03/03/2020

FIR Submit Date: 03/04/2020

FIR Status: _____

Inspected Operator Information:

Company Name: WARD & SON* ALFRED

Company Number: 94300

Address: P O BOX 737

City: OGALLALLA State: NE Zip: 69153

LOCATION - Location ID: 317229

Location Name: STATE-63S52W Number: 3SESW County: WASHINGTON

Qtrqr: SESW Sec: 3 Twp: 3S Range: 52W Meridian: 6

Latitude: 39.815600 Longitude: -103.193160

FACILITY - API Number: 05-121- -00 Facility ID: 237305

Facility Name: STATE Number: 4

Qtrqr: SESW Sec: 3 Twp: 3S Range: 52W Meridian: 6

Latitude: 39.815600 Longitude: -103.193160

CORRECTIVE ACTIONS:

1 CA# 136937

Corrective Action: Install sign to comply with Rule 210.d.

Date: 04/06/2020

Response: CA COMPLETED

Date of Completion: 04/06/2020

Produced water tank labels have been updated and placed the tank.

Operator
Comment:

COGCC Decision:

COGCC
Representative:

2 CA# 136938

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Remove and properly dispose of stained soil in treater shed.

Date: 03/26/2020

Response: CA COMPLETED

Date of Completion: 03/26/2020

Operator
Comment:

All valves, pipes and fittings are securely fasten and are regularly inspected per Rule 605.d

COGCC Decision:

COGCC
Representative:

3 CA# 136939

Corrective Action: Perform successful mechanical integrity test. If a successful MIT can not be performed within 30 day CA time the well must be plugged within 3 months per Rule 326 and 208.

Date: 04/06/2020

Response: CA COMPLETED

Date of Completion: 04/01/2020

Operator
Comment:

Well was SI from 2/1/2019 and was returned to production on 4/1/2020. During time of inspection, the pumping unit was being replaced. As mentioned in Inspection done on 5/13/2023, Document #688307855, "well is pumping by electric motor".

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Well was SI for less than 2 years due to pumping equipment being upgraded. Other Corrective Actions were completed prior to Impetro Operating acquiring the location.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Amber Barnett

Signed:

Title: Compliance Specialist

Date: 12/21/2023 1:56:11 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files