

Construction and Stormwater Inspection

Date: 12/20/2023

Operator: CIVITAS NORTH LLC - 10661

Location ID: 454749

Inspection Document #: 708200771

Weld County, CO

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Hunt Fed 8-60 19 Pad
Location ID: 454749



Photo 1. Taken from the entrance to the location. A copy of the approved From 2A was not posted on location as required by Rule 406.c. The only document within the mailbox was a Weld County grading permit.

Inspection Photos
Location Name:Hunt Fed 8-60 19 Pad
Location ID: 454749



Photo 2. Taken from the northeast corner of the location. Photo illustrates that a perimeter stormwater control (ditch and berm) has been constructed around the entire perimeter of the disturbance area. Also pictured, the eastern side of the topsoil stockpile.

Inspection Photos
Location Name: Hunt Fed 8-60 19 Pad
Location ID: 454749



Photos 3 & 4. Taken from the northern/center portion of the disturbance area. The topsoil stockpile appears to have been previously seeded/mulched with evidence of drill rows. However, during this inspection, it was observed that the topsoil stockpile is predominantly bare/exposed soils with undesirable vegetation (e.g. russian thistle and kochia) observed throughout. Additional revegetation/stabilization techniques are required to prevent wind and water erosion degradation.

Inspection Photos
Location Name:Hunt Fed 8-60 19 Pad
Location ID: 454749



Photo 5. Taken from the top of the stockpile, facing east. See comments in Photos 3 & 4.

Inspection Photos
Location Name:Hunt Fed 8-60 19 Pad
Location ID: 454749



Photo 6. Continued from Photo 5, facing west; See comments in Photos 3 & 4.

Inspection Photos
Location Name:Hunt Fed 8-60 19 Pad
Location ID: 454749



Photo 7. Taken from the northwest corner of the disturbance area. A temporary stormwater control/BMP (ditch and berm) has been constructed around the entire perimeter of the location.

Inspection Photos
Location Name:Hunt Fed 8-60 19 Pad
Location ID: 454749



Photo 8. Taken from the southwest corner of the disturbance area, facing the stormwater detention area.

Inspection Photos
Location Name:Hunt Fed 8-60 19 Pad
Location ID: 454749



Photo 9. Red outlined area represents the stormwater detention area. Portions of the earthen berms require additional stabilization techniques to prevent wind and water erosion as they are comprised of bare/exposed soils.

Inspection Photos
Location Name: Hunt Fed 8-60 19 Pad
Location ID: 454749



Photo 10. Taken within the stormwater detention area. Photo illustrates the outflow culvert and rip rap overflow. See also comments in previous photo.

Inspection Photos
Location Name: Hunt Fed 8-60 19 Pad
Location ID: 454749



Photo 11. Taken from the southeast corner of the disturbance area. Photo illustrates that the temporary stormwater ditch and berm has been installed throughout the entire perimeter of the location.

Inspection Photos
Location Name:Hunt Fed 8-60 19 Pad
Location ID: 454749



Photo 12. Taken from the center portion of the drilling areas. Photo illustrates six (6) wells have been drilled.