

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PA-66S95W/33NESW

Location ID: 335316

Date: 12/18/2023



Location Entrance – Photo #08271



Wellheads – Photo #08272

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PA-66S95W/33NESW

Location ID: 335316

Date: 12/18/2023



Separators – Photo #08279



Tank Battery – Photo #08276

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PA-66S95W/33NESW

Location ID: 335316

Date: 12/18/2023



Rill Erosion Transporting Sediment Off Location – Photo #08280



Lack of Stabilization – Photo #08274

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PA-66S95W/33NESW

Location ID: 335316

Date: 12/18/2023



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #08275