

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, EXXON-66S95W/32NESE

Location ID: 335296

Date: 12/18/2023



Wellheads – Photo #08297



Separators – Photo #08294

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, EXXON-66S95W/32NESE

Location ID: 335296

Date: 12/18/2023



Tank Battery – Photo #08295



Lack of Stabilization – Photo #08299

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, EXXON-66S95W/32NESE

Location ID: 335296

Date: 12/18/2023



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #08300