

Inspection Photos

Location Name: CAERUS PICEANCE LLC N PARACHUTE EF12A-19 L19595 Pad

Location #: 335635



Dec 21, 2023 at 1:01:52 PM



Dec 21, 2023 at 1:01:58 PM

Photo # 691 From entrance to location

Photo # 692 From entrance to location

Inspection Photos

Location Name: CAERUS PICEANCE LLC N PARACHUTE EF12A-19 L19595 Pad

Location #: 335635



Photo # 693 Location



Photo # 694 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC N PARACHUTE EF12A-19 L19595 Pad

Location #: 335635



Photo # 695 Location



Photo # 696 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC N PARACHUTE EF12A-19 L19595 Pad

Location #: 335635



Photo # 697 PRV & Rupture disc vent lines lack caps



Photo # 698 PRV & Rupture disc vent lines lack caps

Inspection Photos

Location Name: CAERUS PICEANCE LLC N PARACHUTE EF12A-19 L19595 Pad

Location #: 335635



Photo # 699 Open ended load line



Photo # 700 Open ended load line

Inspection Photos

Location Name: CAERUS PICEANCE LLC N PARACHUTE EF12A-19 L19595 Pad

Location #: 335635



Photo # 701 Open ended load line