

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/21/2023

Submitted Date:

12/24/2023

Document Number:

708902608**FIELD INSPECTION FORM**Loc ID 335635 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

25 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290079	WELL	PR	09/01/2020	GW	045-13967	N PARACHUTE EF12A-19 L19595	PR
290080	WELL	PR	09/01/2020	GW	045-13966	N PARACHUTE EF12B- 19L19595	PR
291691	WELL	PR	09/01/2020	GW	045-14496	N PARACHUTE EF05B- 19L19595	PR
291692	WELL	PR	09/01/2020	GW	045-14495	N PARACHUTE EF05D- 19L19595	PR
291697	WELL	PR	09/01/2020	GW	045-14493	N PARACHUTE EF04D- 19L19595	PR

General Comment:**CECMC Inspection Report Summary**

On 12/21/2023 at approximately 13:01 hours, I, Compliance Specialist, Wayne Smelser

Conducted an on-site inspection at CAERUS PICEANCE LLC N PARACHUTE EF12A-19 L19595 Pad.

Location # 335635 in Garfield County Colorado.

Location is within High Priority/Density/NSO/Black Bear Habitat areas.

Location is approximately 86 yards from Middle Fork Parachute Creek.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Equipment - Multiple open ended load lines with a CA date of 12/31/2023
2. Equipment - PRV & Rupture disc vent lines lack caps with a CA date of 12/31/2023

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-2615

Corrective Action:

Date: _____

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Jersey barriers		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Gas lift meter house - Jersey barriers		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Jersey barriers		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 6		
Comment: Sales			
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Other	# 2		
Comment: PRV & Rupture disc vent lines lack caps			
Corrective Action: Vents on pressure safety devices will be designed to be clear and free of debris and water at all times.		Date:	12/31/2023
Type: Other	# 3		
Comment: Open ended load lines			
Corrective Action: All load lines will be capped or plugged		Date:	12/31/2023
Type: Bradenhead	# 5		
Comment: Taylor plugs located on all bradenhead. All bradenhead valves are accessible.			
Corrective Action:		Date:	
Type: Gas Meter Run	# 5		
Comment: Gas lift			
Corrective Action:		Date:	
Type: Plunger Lift	# 5		
Comment: All wells on plunger lift			
Corrective Action:		Date:	
Type: Other	# 1		
Comment: Telemetry			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 6		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	OTHER	STEEL AST		,	
Comment: Centralized containment						
Corrective Action:				Date:		

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	250 bbls	
Other (Type)		

Berms

Inspector Name: Smelser, Wayne

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent			
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	300 BBLs	STEEL AST		,	
Comment:	Centralized containment					
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent			
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				Sparse to none in sections
		Ditches				
		Compaction				
		Culverts				
Ditches						
Berms						
Retention Ponds						
Compaction						Light compaction
Gravel						Sparse to none in areas
		Retention Ponds				
		Rip Rap				

Comment: [Places with sparse to no gravel & light compaction are present on location. Sparse gravel and light compaction could lead to future stabilization and tracking issues.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Please refer to Equipment for observed compliance issues.	smelserw	12/24/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708902609	Inspection 708902608 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6370904
708902610	Inspection 708902608 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6370905