

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

12/18/2023

Submitted Date:

12/18/2023

Document Number:

696305524

FIELD INSPECTION FORM
 Loc ID 418173 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

17 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
418170	WELL	TA	05/10/2019	OW	123-31845	Antelope 18I	TA
418218	WELL	TA	05/15/2019	OW	123-31856	Antelope 43-18	TA
418235	WELL	TA	05/10/2019	OW	123-31860	Antelope 44-18	TA

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	All 3 Wellhead Signs have faded Well Information is no longer visible; see photos		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	01/19/2024
Type	CONTAINERS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	West Side Tanks - NFPA Labels have all faded and peeled; no longer visible. See photos		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	01/19/2024

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	Unused Separator Parts and Equipment at Separators; see photos		
Corrective Action:	Comply with Rule 606	Date:	01/02/2024
Type	UNUSED EQUIPMENT		
Comment:	Unmarked 2" and 1" Risers at Separators and 1" Risers at Wellhead. See photos		
Corrective Action:	Complete flowline and crude oil transfer line abandonments to comply with Rule 1105.	Date:	01/02/2024

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Panels		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

Equipment:				corrective date
Type: Bird Protectors	# 13			
Comment:				
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 6			
Comment:				
Corrective Action:				Date:
Type: Other	# 3			
Comment:	TA Wellheads			
Corrective Action:				Date:
Type: Bradenhead	# 3			
Comment:	Appear to be plumbed to surface			
Corrective Action:				Date:
Type: Other	# 1			
Comment:	Glycol Unit at Compressor			
Corrective Action:				Date:
Type: Emission Control Device	# 6			
Comment:				
Corrective Action:				Date:
Type: VRT	# 1			
Comment:				
Corrective Action:				Date:
Type: Compressor	# 1			
Comment:				
Corrective Action:				Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	500 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares berm with the Crude Oil Tanks			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	OTHER	BV CONCRETE		,	
Comment:						
Corrective Action:						Date:
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)		60 BBLS				
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:		Shares berm with the Crude Oil Tanks				
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	10	500 BBLS	STEEL AST		40.395660,-104.359710	
Comment:						
Corrective Action:						Date:
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Comment:						
Corrective Action:						Date:
<u>Venting:</u>						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
<u>Flaring:</u>						
Type						
Comment:						
Corrective Action:						Date:

Inspected FacilitiesFacility ID: 418170 Type: WELL API Number: 123-31845 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: TA since 05.10.2019 - MIT: 04.08.2021
Form 6A 403213997 with Plug Due Date 12.31.2029

Corrective Action: _____ Date: _____

Facility ID: 418218 Type: WELL API Number: 123-31856 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: TA since 05.15.2019 - MIT: 04.08.2021
Form 6A 403213997 with Plug Due Date 12.31.2029

Corrective Action: _____ Date: _____

Facility ID: 418235 Type: WELL API Number: 123-31860 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: TA since 05.10.2019 - MIT: 04.08.2021
Form 6A 403213997 with Plug Due Date 12.31.2029

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
Gravel		Gravel				
Seeding						

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Routine Field Inspection. * All West Side of Crude Oil Tanks - NFPA Labels have faded and peeled away no longer visible. * All three Wellhead Signs have faded no longer visible. * Unmarked Risers at Separators and Wellheads * Unused Separators Parts and Equipment at Separators	petrie	12/18/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403627464	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6359382
696305525	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6359370