

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/18/2023

Submitted Date:

12/18/2023

Document Number:

696305536

FIELD INSPECTION FORMLoc ID 413458 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
412528	WELL	TA	06/02/2021	GW	123-30512	ANTELOPE 14-19	TA

General Comment:

Follow-Up Inspection to 696305116 dated 07.17.2023

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical Container at Gas Lift Injection Meter House missing Label; see photos		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	01/19/2024

Emergency Contact Number:

Comment:

Corrective Action: Date:

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unmarked OOSLAT Risers at 14-19 Wellhead; see photos		
Corrective Action:	Complete flowline and crude oil transfer line abandonments to comply with Rule 1105.	Date:	01/02/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Panels		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 412528 Type: WELL API Number: 123-30512 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: TA - Since 06.02.2021. MIT - 03.25.2021
Form 6A - 403213997 with a Plug Due Date of 12.31.2029

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<u>Routine Field Follow-Up Inspection. Tumbleweeds have been removed and Riser on Eastside of Location has been tagged.</u> <u>New Corrective Actions: Unmarked OOSLAT Risers at 14-19 Wellhead. Chemical Container at Gas Lift Injection Meter House is missing Labels.</u>	petrie	12/18/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403628927	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6360824
696305537	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6360814