

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/18/2023

Submitted Date:

12/18/2023

Document Number:

702402617

FIELD INSPECTION FORMLoc ID 413346 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

12 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		ECMCInspections@Oxy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
413322	WELL	SI	09/01/2021	OW	123-30664	KUNZMAN W 05-09	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	adequate beginning to fade and will need to be replaced in the near future.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Good Housekeeping:		
Type	WEEDS	
Comment:	Undesirable dead vegetation around the WH and Tank battery location/equipment.	
Corrective Action:	Comply with rule 606	Date: 12/26/2023

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:		
Type	TANK BATTERY	
Comment:	barb wire	
Corrective Action:		Date:
Type	IGNITOR/COMBUSTOR	
Comment:	barb wire	
Corrective Action:		Date:
Type	SEPARATOR	
Comment:	barb wire	
Corrective Action:		Date:
Type	WELLHEAD	
Comment:	Ag panel	
Corrective Action:		Date:

Equipment:			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 6		
Comment:	automation		
Corrective Action:		Date:	

Type: Bird Protectors	# 3	
Comment:		
Corrective Action:		Date:
Type: Emission Control Device	# 1	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment:	appears plumbed to surface	
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	PBV CONCRETE		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	48 bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	shares containment with crude tanks			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		40.167010,-104.791710
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				

Inspected FacilitiesFacility ID: 413322 Type: WELL API Number: 123-30664 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI/LOTO Form 06A Doc # 403108165.

Corrective Action: _____

Date: _____

BradenHeadDate of Last Brhd Test: 05/09/2023Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 1Fluid Type: NoneEnd Surf Csg Pressure: --

Comment: _____

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>On Thursday 12-14-2023 at approximately 1300 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: The Inspection submission date is on 12-18-2023.</p> <p>Operator: Oxy/Kerr McGee</p> <p>Location name:</p> <p>Location ID # 413346</p> <p>Well Name: Kunzman W 05-09</p> <p>API # 05-123-30664</p> <p>County: Weld</p> <p>Weather: Cloudy.</p> <p>Location: Dry.</p> <p>While there, I observed a wellsite and tank battery, SI/LOTO at the time of the inspection.</p> <p>During this inspection, I observed the following possible compliance issues:</p> <p>606 housekeeping: CA date 12-26-2023.</p> <p>See attached photos.</p> <p>A follow up site inspection is needed to ensure that the addressed Compliance issues comply with ECMC rules.</p>	revasr	12/18/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403627739	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6359544
702402618	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6359521