

# Interim Reclamation and Stormwater Inspection

Date: 12/20/2023

Operator: NOBLE ENERGY INC - 100322

Location ID: 427008

Inspection Document #: 708200775

Weld County, CO

Dylan Edwardson  
Reclamation Specialist, ECMC



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: State 8-60 16-2H  
Location ID: 427008




**Photo 1.** Stained soil observed at wellhead.



**Photo 2.** Unused equipment observed near wellhead.

Inspection Photos  
Location Name: State 8-60 16-2H  
Location ID: 427008



**Photo 3.** Unused equipment observed near wellhead.

Inspection Photos  
Location Name: State 8-60 16-2H  
Location ID: 427008



**Photo 4.** It appears the location is in the process of being decommissioned as the former tank battery equipment has been removed.

Inspection Photos  
Location Name: State 8-60 16-2H  
Location ID: 427008



**Photo 5.** Northern interim areas appear to have been recently mowed. A follow-up inspection will be conducted during the active growing season to verify vegetative compliance with Rule 1003, and is therefore “In-process”.

Inspection Photos  
Location Name: State 8-60 16-2H  
Location ID: 427008



**Photo 6.** Eastern interim areas, facing south. See comments in Photo 5.

Inspection Photos  
Location Name: State 8-60 16-2H  
Location ID: 427008



**Photo 7.** Taken from the center portion of the topsoil stockpile, facing north. The stockpile does not comply with Rule 1002.c as evidenced by bare/exposed soils. Additional BMPs and/or revegetation activities are required in order to comply with Rule 1002.c.

Inspection Photos  
Location Name: State 8-60 16-2H  
Location ID: 427008



**Photo 8.** Taken from the center portion of the topsoil stockpile, facing south. See comments in Photo 7.