

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/27/2023

Submitted Date:

12/27/2023

Document Number:

695108958

## FIELD INSPECTION FORM

 Loc ID 308394 Inspector Name: Beardslee, Tom On-Site Inspection  2A Doc Num: \_\_\_\_\_
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

5 Number of Comments

0 Number of Corrective Actions

 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Operator Information:**

OGCC Operator Number: 10705

Name of Operator: EVERGREEN NATURAL RESOURCES LLC

Address: 1875 LAWRENCE ST STE 1150

City: DENVER State: CO Zip: 80202

**Contact Information:**

| Contact Name            | Phone        | Email                      | Comment                         |
|-------------------------|--------------|----------------------------|---------------------------------|
| Distribution, Evergreen | 719-846-7898 | cogcc.evergreen@enrllc.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name       | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 270857      | WELL | PR     | 08/01/2023  | GW         | 071-07967 | DUNLOP 44-19        | PR          |
| 274256      | PIT  | AC     | 10/21/2004  |            | -         | DUNLOP 44-19 ONSITE | AC          |

**General Comment:**

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

| <b>Spills:</b> |      |        |  |  |  |
|----------------|------|--------|--|--|--|
| Type           | Area | Volume |  |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

| <b>Equipment:</b>         |   |  | corrective date |
|---------------------------|---|--|-----------------|
| Type: Progressive Cavity  | # 1   |  |                 |
| Comment:                  |   |  |                 |
| Corrective Action:        |   |  | Date:           |
| Type: Prime Mover         | # 1   |  |                 |
| Comment:                  |   |  |                 |
| Corrective Action:        |   |  | Date:           |
| Type: Vertical Separator  | # 1   |  |                 |
| Comment:                  |   |  |                 |
| Corrective Action:        |   |  | Date:           |
| Type: Ancillary equipment | # 1   |  |                 |
| Comment:                  |   |  |                 |
| Corrective Action:        |   |  | Date:           |
| Type: Bradenhead          | # 1   |  |                 |
| Comment:                  | IS ACCESSABLE   |  |                 |
| Corrective Action:        |   |  | Date:           |
| Type: Gas Meter Run       | # 1   |  |                 |
| Comment:                  | CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR. |  |                 |
| Corrective Action:        |   |  | Date:           |
| Type: Deadman # & Marked  | # 4   |  |                 |
| Comment:                  |   |  |                 |
| Corrective Action:        |   |  | Date:           |

**Venting:**

|                    |    |  |       |
|--------------------|----|--|-------|
| Yes/No             | NO |  |       |
| Comment:           |    |  |       |
| Corrective Action: |    |  | Date: |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |



**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |
| Compaction       | Pass            | Compaction              | Pass                  |               |                          |         |

Comment:

Corrective Action:  Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: 274256 Lat: 37.151893 Long: -104.706344

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_

Comment:

Corrective Action  Date: \_\_\_\_\_

**Fencing:**

Fencing Type: None Fencing Condition: \_\_\_\_\_

Comment:

Corrective Action  Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_ Netting Condition: \_\_\_\_\_

Comment:

Corrective Action  Date: \_\_\_\_\_

Anchor Trench Present: NO Oil Accumulation: NO 2+ feet Freeboard: YES

Comment:

Corrective Action  Date: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description  | URL   |
|--------------|--------------|---|
| 695108959    | INSP. PHOTOS | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6374690">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6374690</a> |