

Interim Reclamation and Stormwater Inspection

Date: 12/15/23

Operator: Bonanza Creek Energy Operating
Company LLC - 8960

Location ID: 429060

Inspection Document #: 713900195

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: North Platte I-24 Pad

Location ID: 429060



Colorado Energy & Carbon Management
Commission
Weld County
+40.3781,-104.3895
150° SE
12/15/23, 1:39 PM



Colorado Energy & Carbon Management
Commission
Weld County
+40.3789,-104.3879
99° E
12/15/23, 1:46 PM

Photo 1. The photo was taken at the entrance to the well location facing Southeast. The photo illustrates the operator signage.

Photo 2. The photo was taken at the center of the well location facing East. The photo illustrates a berm around the pad with tumbleweeds growing along it as well as equipment being used in construction on location.

Inspection Photos

Location Name: North Platte I-24 Pad

Location ID: 429060



Colorado Energy & Carbon Management
Commission
Weld County
+40.3788, -104.3879
124° SE
12/15/23, 1:46 PM



Colorado Energy & Carbon Management
Commission
Weld County
+40.3788, -104.3873
33° NE
12/15/23, 1:47 PM

Photo 3. The photo was taken at the center of the well location facing Southeast. The photo illustrates bare areas of bare soil at the location.

Photo 4. The photo was taken at the East end of the well location facing Northeast. The photo illustrates a bare slope that is part of their construction area.

Inspection Photos

Location Name: North Platte I-24 Pad

Location ID: 429060



Photo 5. The photo was taken at the East end of the well location facing South. The photo illustrates the top of the topsoil stockpile is dominated by tumbleweeds and bare soil.

Photo 6. The photo was taken at the East end of the well location facing Northeast. The photo illustrates a representative sediment trap photo that is covered in tumbleweeds. At the well location there are 4 sediment traps that all need repair and new straw wattle.

Inspection Photos
Location Name: North Platte I-24 Pad
Location ID: 429060



Photo 7. The photo was taken at the East end of the well location facing Southwest. The photo illustrates the side of the topsoil stockpile is dominated by bare soil and tumbleweeds.

Photo 8. The photo was taken at the South end of the well location facing West. The photo illustrates the interim areas are dominated by tumbleweeds and bare soil.

Inspection Photos

Location Name: North Platte I-24 Pad

Location ID: 429060



Colorado Energy & Carbon Management
Commission
Weld County
+40.3782, -104.3886
290° W
12/15/23, 1:56 PM



Colorado Energy & Carbon Management
Commission
Weld County
+40.3782, -104.3894
126° SE
12/15/23, 1:57 PM

Photo 9. The photo was taken at the South end of the well location facing West. The photo illustrates mud being stored on the well location.

Photo 10. The photo was taken at the entrance of the well location facing Southeast. The photo illustrates a partially buried pipe with no cap.

Note - ECMC staff had a conversation with a representative Civitas on location that mentioned once the mud from the vacuum truck dried out the material would be spread back on location.

Inspection Photos

Location Name: North Platte I-24 Pad

Location ID: 429060



Colorado Energy & Carbon Management
Commission
Weld County
+40.3791, -104.3883
154° SE
12/15/23, 2:08 PM



Colorado Energy & Carbon Management
Commission
Weld County
+40.3797, -104.3890
317° NW
12/15/23, 2:03 PM

Photo 11. The photo was taken at the center of the well location facing Southeast. The photo illustrates a tank without proper labels.

Photo 12. The photo was taken at the North side of the well location facing Northwest. The photo illustrates Puncturevine growing along the Northern edge of the well location.