

Interim Reclamation and Stormwater Inspection

Date: 12/26/23

Operator: Extraction Oil & Gas Inc - 10459

Location ID: 458215

Inspection Document #: 713900226

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: VIC 20-E Pad
Location ID: 458215



Photo 1. The photo was taken at the entrance to the well location facing South. The photo illustrates the locations entrance and operator signage.

Photo 2. The photo was taken from the well location facing Northwest. The photo illustrates the wellheads.

Inspection Photos
Location Name: VIC 20-E Pad
Location ID: 458215



Photo 3. The photo was taken from the well location facing Southeast. The photo illustrates unused equipment and debris on location.

Photo 4. The photo was taken from the well location facing Southwest. The photo illustrates a representative marked culvert used for the surface owner to access the neighboring ag field.

Inspection Photos
Location Name: VIC 20-E Pad
Location ID: 458215



Photo 5. The photo was taken from the well location facing South. The photo illustrates the access road connecting the tank battery and well locations.

Photo 6. The photo was taken from the tank battery location facing South. The photo illustrates the ditch and berm that runs along the West side of the tank battery location to the sediment trap as well as the rip rap check dams placed along it.

Inspection Photos
Location Name: VIC 20-E Pad
Location ID: 458215



Colorado Energy & Carbon Management
Commission
Weld County
+40.5578,-104.9093
152° SE
12/26/23, 1:56 PM



Colorado Energy & Carbon Management
Commission
Weld County
+40.5580,-104.9084
347° N
12/26/23, 1:59 PM

Photo 7. The photo was taken from the tank battery location facing Southeast. The photo illustrates the run in to the sediment trap as well as a rip rap check dam that is sedimented in.

Photo 8. The photo was taken from the tank battery location facing North. The photo illustrates the Eastern interim area has been mowed.



Photo 9. The photo was taken from the tank battery location facing Northeast. The photo illustrates the straw wattle protecting the culvert at the entrance needs repair.