

**KT Resources LLC  
Ant Hill Unit 24-43  
Loc ID: 316314**



**Access road to location**



**Entrance to location**



KT Resources LLC  
Ant Hill Unit 24-43  
Loc ID: 316314



**Debris. Leaking fire tube.**



**Staining below fire tube**



**KT Resources LLC  
Ant Hill Unit 24-43  
Loc ID: 316314**



**Lube oil label needs replaced**




**Debris. Oily waste and staining on and around wellhead.**

**KT Resources LLC**  
**Ant Hill Unit 24-43**  
**Loc ID: 316314**



**As signs are replaced additional information will be required**



## Gas calibration overdue



**KT Resources LLC  
Ant Hill Unit 24-43  
Loc ID: 316314**



**Location from Southeast corner**



**Location from Northeast corner**



**KT Resources LLC  
Ant Hill Unit 24-43  
Loc ID: 316314**



**Location from Northwest corner**



**Location from Southwest corner**