

B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S
Reclamation Assessment and Stormwater Inspection																	
Inspection Date	12/18/2023																
Inspector	Levi Johnson, Fortress DS																
Location	Duncan D 11-12																
Well ID	328396																
Location Description	FROM CR 53 and CR 34 AT ENTRANCE TO GUTTERSEN RANCH CONT E/ ON WALL STREET 2 MILES, CONT NE/ 800 FT ON THE ACCESS RD TO LAT/LONG 40.234178/-104.525871																
Reclamation Status	Location is mowed, annual and perennial vegetation is evident																
Vegetation	Location is in final reclamation phase, perennial vegetation beginning to establish																
Stormwater	No stormwater issues observed																
Other	none																
Remarks	Monitor establishment of perennial grasses and forbs, implement weed control plan and mowing for annual weeds																
Stormwater	In response to ECOMC Inspection 712900141, location was mowed and innerseeded with Sandy Loam Native Mix applied at 20 lbs/acre.																
Other	Below, where that mowing and innerseeding have been done																



From center of pad facing NE\*



From center of pad facing E\*



From center of pad facing SW\*



From center of pad facing N\*\*



From center of pad facing S\*\*



From center of pad facing S\*\*



From center of pad facing S\*\*

\*Pictures on this page represent the site on the NW side of the road

\*\*Pictures on this page represent the site on the SE side of the road