

FORM INSP Rev X/20	State of Colorado Oil and Gas Conservation Commission 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109	 	Inspection Date: <u>12/29/2023</u> Submitted Date: <u>12/29/2023</u> Document Number: <u>707602206</u>
FIELD INSPECTION FORM			

Loc ID 414330 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

10 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:

OGCC Operator Number: 100322
 Name of Operator: NOBLE ENERGY INC
 Address: 2001 16TH STREET SUITE 900
 City: DENVER State: CO Zip: 80202

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		rbucogccinspectionreports@chevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
414323	WELL	TA	01/01/2022	OW	123-30730	TREBOR B 11-18	TA

General Comment:

This is a WELL inspection. (AMI: Alternate Method Inspection).
 Well(s): 1: Temporarily Abandoned | TA.
 Battery: Inactive | Shut-down.

Centralized Battery serves 5 Location IDs (326889, 326886, 414330, 414332, 414334).
 (Well(s): 5: Temporarily Abandoned | TA).

Centralized Battery Formerly served 2 Location IDs (310601, 323768).
 (Well(s): 2: Plugged & Abandoned | PA).

Centralized Battery serves 1 Tank Battery Facility ID (Pending).

Reference:
 Fwp-C.) Follow-up to Field Inspection Report doc. #707602124 dated 11/29/2023.
 A.) Field Inspection Report doc. #707602120 and/or Location ID #326889 for TA Well(s) info.
 B.) Field Inspection Report doc. #707602122 and/or Location ID #326886 for TA Well(s) info.
 C.) Field Inspection Report doc. #707602124 and/or Location ID #414330 for TA Well(s) info.
 D.) Field Inspection Report doc. #707602126 and/or Location ID #414332 for TA Well(s) info.
 E.) Field Inspection Report doc. #707602129 and/or Location ID #414334 for TA Well(s) info.
 F.) Field Inspection Report doc. #707602131 and/or Location ID #310601 for PA Well(s) info.
 G.) Field Inspection Report doc. #707602133 and/or Location ID #326889 for Battery / Facility, Equipment info.

Location			
Lease Road:			
	Type	Access	
	comment:	Adequate	
	Corrective Action:		Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
	Type	WELLHEAD	
	Comment:		
	Corrective Action:		Date:
Emergency Contact Number:			
	Comment:	<input style="width: 500px;" type="text"/>	
	Corrective Action:	<input style="width: 500px;" type="text"/>	Date: _____
Good Housekeeping:			
Type	WEEDS		
Comment:	Prior insp: Overgrown vegetation at wellsite. Refer to Rule 606.c for guidance. *Remove, manage, & control overgrown vegetation around wellsite. Comply with Rule 606.c. Corrective Action date: 01/02/2024. (30-days). See photo #1. This insp: **Overgrown vegetation at wellsite NOW mitigated as of 12/08/2023. See photo(s) #1-2. Photo #2 (Operator photo).		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
	Comment: <input style="width: 600px;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
	Type	WELLHEAD	
	Comment:	Iron panel.	
	Corrective Action:		Date:
Equipment:			
Type: Other	# 1		corrective date
Comment:	Wellhead: w/ Master, casing valves.		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:			Date:

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.416741,-104.523329
Comment:	Centralized Battery serves 5 Location IDs (326889, 326886, 414330, 414332, 414334). (Well(s): 5: Temporarily Abandoned TA). Centralized Battery serves 1 Tank Battery Facility ID (Pending).				
Corrective Action:					Date:

Paint	
Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:

Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities

Facility ID: 414323 Type: WELL API Number: 123-30730 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Temporarily Abandoned | TA.
Disconnected from flowline.
Battery: Inactive | Shut-down.
Locked-Out, Tagged-Out | LOTO.
Blue TA tag posted.
CECMC records last production: 04/2020.

Form 4 on file. TA date: 10/30/2021. Approved.
DH-CIBP set.
Form 21 MIT on file. MIT date: 11/03/2021. Approved.
Form 6A on file. Out-of-Svc Designation.
Date: 04/01/2020. Approved.

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: 04/09/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Comment: <input style="width: 90%;" type="text"/>						
Corrective Action: <input style="width: 90%;" type="text"/>						Date: _____
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments

Comment	User	Date
<p>CECMC Inspection Report Summary:</p> <p>On FRI 12/29/2023 at approximately 13:30 hrs. I, Bret Evins, conducted an AMI: Alternate Method inspection at: Operator Name: NOBLE ENERGY INC Location Name: TREBOR B/11-18 Location ID: 414330 Well Name(s): Trebor B 11-18. API: 123-30730. Location County: Weld County, Colorado Weather: Partly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 5 Location IDs (326889, 326886, 414330, 414332, 414334). (Well(s): 5: Temporarily Abandoned TA).</p> <p>Centralized Battery Formerly served 2 Location IDs (310601, 323768). (Well(s): 2: Plugged & Abandoned PA).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (Pending).</p> <p>Reference: Fwp-C.) Follow-up to Field Inspection Report doc. #707602124 dated 11/29/2023. A.) Field Inspection Report doc. #707602120 and/or Location ID #326889 for TA Well(s) info. B.) Field Inspection Report doc. #707602122 and/or Location ID #326886 for TA Well(s) info. C.) Field Inspection Report doc. #707602124 and/or Location ID #414330 for TA Well(s) info. D.) Field Inspection Report doc. #707602126 and/or Location ID #414332 for TA Well(s) info. E.) Field Inspection Report doc. #707602129 and/or Location ID #414334 for TA Well(s) info. F.) Field Inspection Report doc. #707602131 and/or Location ID #310601 for PA Well(s) info. G.) Field Inspection Report doc. #707602133 and/or Location ID #326889 for Battery / Facility, Equipment info.</p>	evinsb	12/29/2023

During this inspection, the following prior possible compliance issue(s) appear to be addressed:

1.) Overgrown vegetation at wellsite.

Refer to Rule 606.c for guidance.

*Remove, manage, & control overgrown vegetation around wellsite.

Comply with Rule 606.c.

Corrective Action date: 01/02/2024. (30-days).

**Overgrown vegetation at wellsite NOW mitigated as of 12/08/2023.

See photo(s) #1-2.

Corrective Action(s), NOW resolved.

Field Inspection Report Resolution | FIRR doc. #403634104 indicates Overgrown vegetation at wellsite NOW mitigated as of 12/08/2023.

Operator provided photo(s) for verification.

Corrective Action(s) have been resolved.

During this inspection, NO New/Current possible compliance issues were observed.

This is a summary of the inspection report.

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707602207	Site photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6376750