

Interim Reclamation and Stormwater Inspection

Date: 12/26/23

Operator: Bayswater Exploration & Production LLC -
10261

Location ID: 454899

Inspection Document #: 713900230

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Drake Pad
Location ID: 454899



Photo 1. The photo was taken from the entrance of the well location facing Northwest. The photo illustrates the operator sign and access road.

Photo 2. The photo was taken from the well location facing Southeast. The photo illustrates the topsoil stockpile appears vegetated but is mowed.

Inspection Photos
Location Name: Drake Pad
Location ID: 454899



Photo 3. The photo was taken from the the well location facing Southeast. The photo illustrates what appears to a be a gravel spoil pile on the pad.

Photo 4. The photo was taken from the well location facing South. The photo illustrates a representative photo of subsidence surrounding the topsoil stockpile likely related to a sound wall.

Inspection Photos
Location Name: Drake Pad
Location ID: 454899



Photo 5. The photo was taken from the the well location facing East. The photo illustrates erosional rills off the pad into the sediment trap.

Photo 6. The photo was taken from the well location facing South. The photo illustrates one area of the pad that should be minimized.

Inspection Photos
Location Name: Drake Pad
Location ID: 454899



Photo 7. The photo was taken from the the well location facing South. Refer to the comment for photo 6.

Photo 8. The photo was taken from the well location facing Southeast. The photo illustrates the cutslope around the perimeter of the pad is temporarily stabilized and has very little vegetation.

Inspection Photos
Location Name: Drake Pad
Location ID: 454899



Photo 9. The photo is Google Earth imagery from June of 2023 of the well location. The photo illustrates the Operator has not yet performed interim reclamation.