

Inspection Photos

Location Name: CAERUS PICEANCE LLC N.PARACHUTE EF15D C27 595 Pad

Location #: 335828



Photo # 1360 From entrance to location



Photo # 1361 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC N.PARACHUTE EF15D C27 595 Pad

Location #: 335828



Photo # 1362 Location



Photo # 1363 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC N.PARACHUTE EF15D C27 595 Pad

Location #: 335828



Photo # 1364 Location



Photo # 1365 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC N.PARACHUTE EF15D C27 595 Pad

Location #: 335828



Photo # 1366 Location



Photo # 1367 Wellhead sign lacks required info

Inspection Photos

Location Name: CAERUS PICEANCE LLC N.PARACHUTE EF15D C27 595 Pad

Location #: 335828



Photo # 1368 Wellhead sign lacks required info



Photo # 1369 Wellhead sign lacks required info