

## Inspection Photos

Location Name: TEP Rocky Mountain LLC WATSON RANCH A Pad

Location # 413055



Photo # 881 From entrance to location




Photo # 882 Location

## Inspection Photos

Location Name: TEP Rocky Mountain LLC WATSON RANCH A Pad

Location # 413055



Photo # 883 Location



Photo # 884 Location



## Inspection Photos

Location Name: TEP Rocky Mountain LLC WATSON RANCH A Pad

Location # 413055



Dec 27, 2023 at 11:44:53 AM  
CO

Photo # 885 Location



Dec 27, 2023 at 11:49:39 AM  
CO

Photo # 886 Location

## Inspection Photos

Location Name: TEP Rocky Mountain LLC WATSON RANCH A Pad

Location # 413055



Photo # 887 Location



Photo # 888 Location



## Inspection Photos

Location Name: TEP Rocky Mountain LLC WATSON RANCH A Pad

Location # 413055



**Photo # 889 Wildlife egress on BAT 14B-17-07-95 well cellar ineffective/needs adjustment**



**Photo # 890 Same wildlife egress from a different angle**



## Inspection Photos

Location Name: TEP Rocky Mountain LLC WATSON RANCH A Pad

Location # 413055



Photo # 891 Debris



Photo # 892 Open ended load line