

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

12/27/2023

Submitted Date:

12/30/2023

Document Number:

708902653

**FIELD INSPECTION FORM**
 Loc ID 413055 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

34 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
413086	WELL	PR	09/17/2010	GW	045-18713	BAT 22D-17-07-95	PR
413087	WELL	PR	10/18/2009	GW	045-18714	BAT 23D17-07-95	PR
413088	WELL	PR	08/01/2022	GW	045-18715	BAT 24B-17-07-95	PR
415492	WELL	PR	07/17/2010	GW	045-19066	BAT 34D-17-07-95	PR
415494	WELL	PR	07/19/2010	GW	045-19067	BAT 14D-17-07-95	PR
415528	WELL	PR	07/18/2010	GW	045-19082	BAT 24D-17-07-95	PR
415545	WELL	PR	01/01/2019	GW	045-19089	BAT 44A-18-07-95	PR
415560	WELL	PR	07/26/2010	GW	045-19095	BAT 23B-17-07-95	PR
415570	WELL	PR	05/21/2011	GW	045-19098	BAT 13D-17-07-95	PR
415573	WELL	PR	09/17/2010	GW	045-19101	BAT 34B-17-07-95	PR
415587	WELL	PR	07/23/2010	GW	045-19108	BAT 13B-17-07-95	PR
415590	WELL	PR	07/18/2010	GW	045-19109	BAT 14B-17-07-95	PR

**General Comment:**

CECMC Inspection Report Summary

On 12/27/2023 at approximately 11:39 hours, I, Compliance Specialist, Wayne Smelser  
Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC WATSON RANCH A Pad.

Location # 413055 in Garfield County Colorado.

Location is within High Priority/Density/Black Bear Habitat areas & in close proximity to NSO Habitat area.

Location is within Rule 411a Surface Water Internal Buffer.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Equipment - Open ended load line with a CA date of 01/06/2024

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical tanks		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	911/970-285-9377		
Corrective Action:		Date:	

<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:	Debris - please refer to photo log		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Wildlife egress on BAT 14B-17-07-95 well cellar ineffective/needs adjustment - please refer to photo log		
Corrective Action:		Date:	

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	6ft security fence		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Barbed wire fence on west side of location showing some signs of disrepair.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Cattle panels		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Other	# 1		
Comment:	Telemetry		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Chemical tanks		
Corrective Action:		Date:	
Type: Bird Protectors	# 6		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 12		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Gas Meter Run	# 12		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 12		
Comment:	Taylor plugs located on all bradenhead. All bradenhead valves are accessible.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 12		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Open ended load line		
Corrective Action:	All load lines will be capped or plugged	Date:	01/06/2024
Type: Deadman # & Marked	# 6		
Comment:	Marked		

Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLS	STEEL AST		,	
Comment:	Centralized containment					
Corrective Action:					Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent		
Comment:				
Corrective Action:			Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	300 BBLS	STEEL AST		,	
Comment:	Centralized containment					
Corrective Action:					Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent		
Comment:				
Corrective Action:			Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type	
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities									
Facility ID:	413086	Type:	WELL	API Number:	045-18713	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	413087	Type:	WELL	API Number:	045-18714	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	413088	Type:	WELL	API Number:	045-18715	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	415492	Type:	WELL	API Number:	045-19066	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	415494	Type:	WELL	API Number:	045-19067	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	415528	Type:	WELL	API Number:	045-19082	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	415545	Type:	WELL	API Number:	045-19089	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	415560	Type:	WELL	API Number:	045-19095	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			

Facility ID:	415570	Type:	WELL	API Number:	045-19098	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	415573	Type:	WELL	API Number:	045-19101	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	415587	Type:	WELL	API Number:	045-19108	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	415590	Type:	WELL	API Number:	045-19109	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			



**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
Compaction						Small areas of light compaction
		Ditches				
Gravel						Sparse in some areas
				Material Handling And Spill Prevention		Chemical tank containments
		Compaction				
		Gravel				Sparse

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<a href="#">Please refer to Equipment for observed compliance issue.</a>	smelserw	12/30/2023

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
708902655	Inspection 708902653 Stormwater photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6377219">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6377219</a>
708902656	Inspection 708902653 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6377220">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6377220</a>