

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/28/2023

Submitted Date:

01/01/2024

Document Number:

701007868

**FIELD INSPECTION FORM**

Loc ID 321860 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 34105  
Name of Operator: GILBERT-STEWART OPERATING LLC  
Address: 1801 BROADWAY STE 200  
City: DENVER State: CO Zip: 80202

**Findings:**

- 5 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Gilbert, Kent	303-534-1686	kgoil@msn.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208258	WELL	TA	09/01/2019	OW	017-07193	MILLER 1	PA

**General Comment:**

[Routine Inspection](#)

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type: DEBRIS

Comment: Misc piping and wellhead laying around location

Corrective Action: Comply with Rule 606

Date: 01/28/2024

Overall Good:

**Spills:**

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type: Ancillary equipment

# 1

corrective date

Comment: Electric panel still on location

Corrective Action: Remove equipment from location

Date: 01/28/2024

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0		FIBERGLASS AST		38.768810,-102.389350

Comment: Tank has been removed from location

Corrective Action:

Date:

**Paint**

Condition:

Other (Content):

Other (Capacity):

Other (Type):

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				

Comment: Berms still present at time of inspection

Corrective Action: Remove berms and begin final reclamation process

Date: 01/28/2024

**Venting:**

Yes/No:

Comment:

Corrective Action:

Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 208258 Type: WELL API Number: 017-07193 Status: TA Insp. Status: PA

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701007879	Wellhead photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6377668">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6377668</a>
701007881	Tank battery location	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6377669">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6377669</a>