

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE EF06D L29 595 Pad

Location #: 335607



Photo # 1151 From entrance to location




Photo # 1152 From entrance to location

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE EF06D L29 595 Pad

Location #: 335607



Photo # 1153 Location



Photo # 1154 Location/blowdown tank



Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE EF06D L29 595 Pad

Location #: 335607



Photo # 1155 Location



Photo # 1156 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE EF06D L29 595 Pad

Location #: 335607



Photo # 1157 Location



Photo # 1158 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE EF06D L29 595 Pad

Location #: 335607



Photo # 1159 Location



Photo # 1160 Hole near wellheads/wildlife & personnel protections insufficient (hole approximately 4-6ft deep)

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE EF06D L29 595 Pad

Location #: 335607



Photo # 1161 Hole near wellheads/wildlife & personnel protections insufficient (hole approximately 4-6ft deep)



Photo # 1162 Debris

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE EF06D L29 595 Pad

Location #: 335607




Photo # 1163 Labeling on blowdown tank missing required info



Photo # 1164 Wellhead signs lack required information



Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE EF06D L29 595 Pad

Location #: 335607



Photo # 1165 Wellhead signs lack required information



Photo # 1166 Wellhead signs lack required information

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE EF06D L29 595 Pad

Location #: 335607




Photo # 1167 Single sign at wellheads insufficient, please refer to signs/marker for observed compliance issue on this & other wellhead signs.

