

Inspection Photos
Location Name: McPeek 0-8-10
Location ID: 422467



Energy & Carbon Management Commission
40.14569, -104.76343, 4937.2ft, 314°
01/02/2024 12:38:56

Photo 1 Location.



Energy & Carbon Management Commission
40.1458, -104.7634, 4878.5ft, 283°
01/02/2024 12:38:30

Photo 2 TB sign.

Inspection Photos
Location Name: McPeck 0-8-10
Location ID: 422467



Photo 3 TB.




Photo 4 Stained soil on the East side of the condensate tank under the hammer union.

Inspection Photos
Location Name: McPeck 0-8-10
Location ID: 422467



Photo 5 Stained soil on the East side of the condensate tank by the load out line.



Photo 6 Stained soil on the East side of the condensate tank by the hole in tank.

Inspection Photos
Location Name: McPeck 0-8-10
Location ID: 422467



Photo 7 Stained soil on the west side of the condensate tank by the access panel.



Photo 8 WH sign faded no emergency information.

Inspection Photos
Location Name: McPeck 0-8-10
Location ID: 422467



Photo9 WH.



Photo 10 Horizontal Heated Separators.

Inspection Photos
Location Name: McPeck 0-8-10
Location ID: 422467



Photo 11 Vertical Separator.



Photo 12 ECDs.

Inspection Photos
Location Name: McPeck 0-8-10
Location ID: 422467



Photo 13 Gas Meter Run, card indicates current calibration.

