

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/02/2024

Submitted Date:

01/02/2024

Document Number:

702402754**FIELD INSPECTION FORM**Loc ID 422467 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10633Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLCAddress: 555 17TH STREET SUITE 3700City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**15 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|-------------------------|---------------------------------|
| , | | ECMCInspections@Oxy.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|-----------------|--------|-------------|------------|-----------|----------------|-------------|
| 431852 | WELL | PR | 12/17/2013 | OW | 123-36821 | McPeek 0-8-10 | PR |
| 471018 | TANK BATTERY | AC | 01/28/2020 | | - | McPeek battery | AC |

General Comment:

LocationOverall Good: ☒

| | | | |
|----------------------|--|-------|------------|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Sign not posted or information inaccurate at well(s) | | |
| Corrective Action: | Install sign to comply with Rule 605.a. | Date: | 02/02/2024 |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | adequate | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | adequate | | |
| Corrective Action: | | Date: | |

| | |
|---------------------------|-------------|
| Emergency Contact Number: | |
| Comment: | |
| Corrective Action: | Date: _____ |

| | | | |
|---------------------------|--|-------|------------|
| Good Housekeeping: | | | |
| Type | OTHER | | |
| Comment: | Stained soils on the west side of the condensate tanks load line | | |
| Corrective Action: | Properly dispose of oily waste in accordance with 905.e. | Date: | 02/02/2024 |

Overall Good: ☐

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | | |
|--------------------|-------------------|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Ag panel | | |
| Corrective Action: | | Date: | |
| Type | TANK BATTERY | | |
| Comment: | barb wire | | |
| Corrective Action: | | Date: | |
| Type | IGNITOR/COMBUSTOR | | |
| Comment: | barb wire | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|-----|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Pig Station | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------------------------|------------------------------------|--|-------|
| Type: Horizontal Heated Separator | # 2 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Vertical Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Bradenhead | # 1 | | |
| Comment: | appears plumbed to surface | | |
| Corrective Action: | | | Date: |
| Type: Bird Protectors | # 4 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Gas Meter Run | # 1 | | |
| Comment: | card indicates current calibration | | |
| Corrective Action: | | | Date: |
| Type: Ancillary equipment | # 7 | | |
| Comment: | automation | | |
| Corrective Action: | | | Date: |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Emission Control Device | # 2 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Tanks and Berms:

| | | | | | | |
|--------------------|---|----------|----------------|---------|--------|-------|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| PRODUCED WATER | 1 | OTHER | FIBERGLASS AST | | , | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |

Paint

| | | | | | |
|------------------|---------|--|--|--|--|
| Condition | | | | | |
| Other (Content) | | | | | |
| Other (Capacity) | 230 bbl | | | | |
| Other (Type) | | | | | |

Berms

| | | | | | | |
|--------------------|--|---------------------|---------------------|-------------|--------|--|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | | |
| Metal | Adequate | Walls Sufficent | Base Sufficient | Adequate | | |
| Comment: | shares containment with condensate tanks | | | | | |
| Corrective Action: | | | | | Date: | |
| Contents | # | Capacity | Type | Tank ID | SE GPS | |

| | | | | | | |
|--------------------|--|-------|-----------|--|-----------------------|------------------|
| CONDENSATE | 3 | OTHER | STEEL AST | | 40.145830,-104.763410 | |
| Comment: | North Tank is rusted, pitted, or show evidence of inadequate repair. Stained soil under pitted hole in tank. | | | | | |
| Corrective Action: | Inspect, maintain and repair tanks to comply with rule 609.b. | | | | | Date: 02/02/2024 |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Metal | Adequate | Walls Sufficent | Base Sufficient | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Wells Served By Facilities Above

| |
|------------|
| API Number |
| 123-36821 |

AirsID

| | |
|------------|--------|
| API Number | AirsID |
|------------|--------|

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | | | | | | | |
|-------------------------|--------|----------------------------|------|------------------------|-----------|-------------|----|---------------|----|
| Facility ID: | 431852 | Type: | WELL | API Number: | 123-36821 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | | PR | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |
| BradenHead | | | | | | | | | |
| Date of Last Brhd Test: | | 08/23/2023 | | Annual Brhd Completed? | | Yes | | | |
| Last Brhd Test Results | | Initial Surf Csg Pressure: | | 10 | | Fluid Type: | | | |
| | | End Surf Csg Pressure: | | 0 | | | | | |
| Comment: | | | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |
| Facility ID: | 471018 | Type: | TANK | API Number: | - | Status: | AC | Insp. Status: | AC |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment | User | Date |
|--|--------|------------|
| <p>ECMC Inspection Report Summary</p> <p>On Tuesday 1-2-2024 at approximately 1240 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection:</p> <p>Operator: Civitas/Crestone Peak Resources</p> <p>Location name:</p> <p>Location ID # 422467</p> <p>Well Name: McPeek 0-8-10</p> <p>API # 05-123-36821</p> <p>County: Weld</p> <p>Weather: Clear</p> <p>Location: Dry</p> <p>While there, I observed a wellsite & tank battery, PR at the time of the inspection.</p> <p>During this inspection, I observed the following possible compliance issues:</p> <p>605.a Signs: CA date 2-2-2024</p> <p>905.e housekeeping: CA date 2-2-2024</p> <p>609.b Crude/Condensate Tanks: CA date 2-2-2024</p> <p>See attached photos.</p> <p>A follow up site inspection is needed to ensure that the addressed Compliance issues comply with ECMC rules.</p> | revasr | 01/02/2024 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------|---|
| 702402755 | location pics | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6378962 |