

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	<input style="width: 100%;" type="text"/>
Corrective Action:	<input style="width: 100%;" type="text"/>
	Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Panels		
Corrective Action:		Date:	

Equipment:		corrective date
Type: Bradenhead	# 1	
Comment:	Appears to be plumbed to surface	
Corrective Action:		Date:
Type: Plunger Lift	# 1	
Comment:	TA - Well has been disconnected from Flowline	
Corrective Action:		Date:

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 299261 Type: WELL API Number: 123-29305 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: TA - 05.26.2020. Form 6A 403118488 dated 08.16.2022 with a Plug Due Date of 12.31.2030

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
Routine Field Inspection	petrie	01/02/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696305625	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6378994