

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/02/2024

Submitted Date:

01/02/2024

Document Number:

707602208

**FIELD INSPECTION FORM**Loc ID 330135 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: ☐**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

16 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
250681	WELL	TA	02/01/2022	GW	123-18484	AMIGO 17-12	PA

**General Comment:**

This is a WELL / BATTERY inspection. (AMI: Alternate Method Inspection).  
Well(s): 1: Plugged & Abandoned | PA.  
Battery: Inactive | Shut-down.

Centralized Battery formerly served 3 Location IDs  
(330135, 302597, 331973).  
(Well(s): 3: Plugged & Abandoned | PA).

Reference:  
Fwp-A.) Follow-up to Field Inspection Report doc. #707602182 dated 12/05/2023.  
A.) Field Inspection Report doc. #707602182 and/or Location ID #330135  
for PA Well(s), Battery / Facility, Equipment info.  
B.) Field Inspection Report doc. #707602184 and/or Location ID #302597  
for PA Well(s) info.  
C.) Field Inspection Report doc. #707602186 and/or Location ID #331973  
for PA Well(s) info.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	OOSLAT / LOTO All Inactive Battery Equipment.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	<p>Prior insp:            Unnecessary equipment at Inactive Battery site.            ALL wells formerly serving Inactive Battery site have been PA'd.            Unnecessary equipment includes:            ALL Produced Oil &amp; H2O tank(s), vault(s), Separator(s), ECD(s), Gas meter run(s), riser (s), etc.            Refer to Rule 606 for guidance.            *Remove unnecessary equipment from Inactive Battery site.            Comply with Rule 606.            Corrective Action date: 05/15/2024. (153 days).            See photo(s) #3, 4, 5.</p> <p>This insp:            **Form 27-I Remediation Workplan on file.            Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.            Chevron Greeley, CO Regulatory Compliance team advised decommissioning work commence date: 01/11/2024.            Corrective Action(s), NOW resolved.</p>		
Corrective Action:		Date:	

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	SEPARATOR		
Comment:	Surrounded by earth berms.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 2		
Comment:	Battery site: 2: ECD scrubber(s).		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Gas Sales: Calibration card(s) indicates calibration > 1 year. Last calibration: 05/28/2021. Inactive, NO production.		
Corrective Action:		Date:	
Type: Plunger Lift	# 0		
Comment:	Well Plugged & Abandoned   PA. Equipment removed.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Flowline valve at PA wellsite. OOSLAT / LOTO.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:	1: Crude storage vapor line combustor(s). Controls crude oil tank(s) vapors. Pilots: OFF   Shut-down. 1: Separator vapor line combustor(s). Controls separator(s) vapors. Pilots: OFF   Shut-down.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	<100 BBLS	CONCRETE SUMP/VAULT		,
Comment:					
Corrective Action:	Date:				

**Paint**

Condition	
Other (Content)	

Inspector Name: Evins, Bret

Other (Capacity) 60 Bbls.						
Other (Type)						
<b>Berms</b>						
Type	Capacity		Permeability (Wall)		Permeability (Base)	Maintenance
Earth	Adequate		Walls Sufficient		Base Sufficient	Adequate
Comment: Berms shared w/ crude oil tank(s), produced H2O vault(s).						
Corrective Action:						Date:
Contents	#	Capacity	Type		Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST			40.492396,-104.572063
Comment: Equalizer line(s) connect crude oil tank(s).						
Corrective Action:						Date:
<b>Paint</b>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity		Permeability (Wall)		Permeability (Base)	Maintenance
Earth	Adequate		Walls Sufficient		Base Sufficient	Adequate
Comment: Berms shared w/ crude oil tank(s), produced H2O vault(s).						
Corrective Action:						Date:
<b>Venting:</b>						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
<b>Flaring:</b>						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities									
Facility ID:	250681	Type:	WELL	API Number:	123-18484	Status:	TA	Insp. Status:	PA

--

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>CECMC Inspection Report Summary:</p> <p>On TUE 01/02/2024 at approximately 15:00 hrs. I, Bret Evins, conducted an AMI: Alternate Method inspection at: Operator Name: NOBLE ENERGY INC Location Name: AMIGO-66N64W/17NWNE Location ID: 330135 Well Name(s): Amigo 17-12. API: 123-18484. Location County: Weld County, Colorado Weather: Mostly Sunny, damp from prior storm.</p> <p>While there, I observed: Well(s): 1: Plugged &amp; Abandoned   PA. Battery: Inactive   Shut-down.</p> <p>Centralized Battery formerly served 3 Location IDs (330135, 302597, 331973). (Well(s): 3: Plugged &amp; Abandoned   PA).</p> <p>Reference: Fwp-A.) Follow-up to Field Inspection Report doc. #707602182 dated 12/05/2023. A.) Field Inspection Report doc. #707602182 and/or Location ID #330135 for PA Well(s), Battery / Facility, Equipment info. B.) Field Inspection Report doc. #707602184 and/or Location ID #302597 for PA Well(s) info. C.) Field Inspection Report doc. #707602186 and/or Location ID #331973 for PA Well(s) info.</p> <p>WELL STATUS COMMENT: Plugged &amp; Abandoned   PA. Form 6-SRA on file. Plugging, cut/cap date: 11/30/2023. Approval Pending. Plugged &amp; Abandoned   PA well GPS coordinates: 40.492015 / -104.572405</p> <p>During this inspection, the following prior possible compliance issue(s) appear to be addressed: 1.) Unnecessary equipment at Inactive Battery site. ALL wells formerly serving Inactive Battery site have been PA'd. Unnecessary equipment includes: ALL Produced Oil &amp; H2O tank(s), vault(s), Separator(s), ECD(s), Gas meter run(s), riser(s), etc. Refer to Rule 606 for guidance. *Remove unnecessary equipment from Inactive Battery site. Comply with Rule 606. Corrective Action date: 05/15/2024. (153 days). See photo(s) #3, 4, 5.</p> <p>**Form 27-I Remediation Workplan on file. Rule 913.c.(9): Decommissioning of Oil and Gas Facilities. Chevron Greeley, CO Regulatory Compliance team advised decommissioning work commence date: 01/11/2024. Corrective Action(s), NOW resolved.</p> <p>During this inspection, NO New/Current possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	01/02/2024

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707602210	Site photo(s)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6379026">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6379026</a>