

Inspection Photos  
Location Name: Roy Dutcher B1  
Location ID: 317870



Photo 1 Wellsite.



Photo 2 WH sign faded and needs replaced.

**Inspection Photos**  
**Location Name: Roy Dutcher B1**  
**Location ID: 317870**



**Photo 3 Stained soil by the WH.**

**Photo 4 Stained soil to the west of the WH.**

Inspection Photos  
Location Name: Roy Dutcher B1  
Location ID: 317870



Photo 5 ancillary equipment.

Photo 6 Tank battery/sign.

**Inspection Photos**  
**Location Name: Roy Dutcher B1**  
**Location ID: 317870**



**Photo 7 Gas Meter Run card indicates current calibration.**

**Photo 8 Stained soil by the TB load out valve**

**Inspection Photos**  
**Location Name: Roy Dutcher B1**  
**Location ID: 317870**



Energy & Carbon Management Commission  
40.11821, -104.84513, 4861.3ft, 321°  
01/03/2024 14:23:53



Energy & Carbon Management Commission  
40.11831, -104.84512, 4866.9ft, 293°  
01/03/2024 14:24:05

**Photo 9 Stained soil by the TB load out valve.**

**Photo 10 Flow line manifold.**

Inspection Photos  
Location Name: Roy Dutcher B1  
Location ID: 317870



Photo 11 Stained soil by the flow line manifold.



Photo 12 Stained soil by the flow line manifold.

**Inspection Photos**  
**Location Name: Roy Dutcher B1**  
**Location ID: 317870**



**Photo 13 ECD.**

**Photo 14 Horizontal Heater Treaters.**